

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# XD9131K

Model:

MITSUBISHI

Accident Date :15/8/2024

Location : NEAR BEF SINGAPORE AVIATION

3P:

SNG6516L (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper	3186.60	dd ✓	
2	1 pc	Front bumper LH garnish (Lower)	610.20	X	
3	1 pc	Front RH head lamp	2818.70	cut ✓	
4	1 pc	Front LH signal lamp	810.20	cut ✓	
5	1 pc	Front RH step garnish	821.70	?	
6	1 pc	Front RH step garnish reflector	120.00	X	
7	1 pc	Front RH step aluminium (lower)	300.00	* dd ✓	
8	1 pc	Front RH step aluminium (upper)	300.00	X	
		Front bumper LH garnish strip 3110 ?			
		Front LH step garnish upper RP			
		Sub Total:	8,967.40	0.00	0.00
			25%	0%	0%
		After Less %:	6,725.55	0.00	0.00
		Labour			
1		To remove and replace damage parts	1200.00	600	
2		To spray painting.	800.00	600	
3		To check wiring.	200.00	50.	
		Sub Total:	2,200.00		
		Total:	8,925.55		
		After Less 20%:	7,140.44		

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



Tanfikh 97495749 / 62563561

WP 22/8/24 at 2:45pm.

2/3 Remedy after repair

3-4 days

tanfikh@kharauto.com



8778 1999
24 hr accident call



PAYNOW

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Complementary item(s) must be resurveyed and subject to final approval from Insurance Company

Noted by Repairer

S a:

Date:

XE9131K ESTIMATEPg1