



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080280/Anh3m4
75 BRAS BASAH ROAD	Date:	24/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 5619Y	Veh. Inspected	SNH 8723L
Policy No.	-	Coverage	0
Claim No.	MT/1290962-002	Excess	\$0.00
Assign From	HELENA TAN	Assign Date	19/08/2024

### 2. Vehicle Details

Make & Model	TOYOTA CAMRY	C.C	2487
Engine No.	A25A5720602	Year of Reg.	02/12/2022
Chassis No.	JTNB23HK003116383	Colour	SILVER
Odometer	43285 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/45R18	BRIDGESTONE	6
L/H Front Tyre	235/45R18	BRIDGESTONE	6
R/H Rear Tyre	235/45R18	BRIDGESTONE	6
L/H Rear Tyre	235/45R18	BRIDGESTONE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	16/08/2024	Inspection Date	19/08/2024 (13:10)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days