

winCar AUTOMOTIVE PTE LTD

Kaki Pakit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAI ENG KEAT
30 TANAH MERAH KECHIL RD #07-09
SINGAPORE 465558

Contact : 96730759

TP INC
Hui Rong

TAX INVOICE

Repair Code : CLM16394

Date in : 16/08/2024

Vehicle Num. : SNH8723L

Model : TOYOTA CAMRY HYBRID 4DR SEDAN (AT) ELEGANCE

Chassis/Eng# : JTNB23HK003116383/A25A5720602

Parts and Labour Assesment

Description of part	Qty	Unit Price	1540 Amount
REAR BOOTLID <i>Buckled</i>	1	1705.90	✓ 1,705.90
REAR BOOTLID 'HYBRID' EMBLEM <i>2</i>	1	74.20	✓ 74.20
REAR BOOTLID 'LOGO' EMBLEM <i>1</i>	1	76.60	✓ 76.60
REAR BOOTLID 'TOYOTA' EMBLEM <i>1</i>	1	76.00	✓ 76.00
REAR BOOTLID HINGES L/R <i>new</i>	2	243.80	X 487.60
REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>	2	32.10	+ 64.20
REAR BOOTLID INNER TRIM GARNISH <i>new</i>	1	441.60	+ 441.60
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	677.60	+ 677.60
REAR BOOTLID REFLECTOR L/R <i>3 new</i>	2	920.70	+ 1,841.40
REAR BOOTLID WEATHER STRIP <i>1 new</i>	1	264.00	+ 264.00
REAR BUMPER <i>Distorted</i>	1	983.40	✓ 983.40
REAR BUMPER LH REFLECTOR <i>crushed</i>	1	130.70	✓ 130.70
REAR BUMPER LOWER OUTER MOULDING L/R <i>crushed</i>	2	130.70	✓ 261.40
REAR BUMPER OUTER SIDE GARNISH L/R <i>crushed</i>	2	41.00	✓ 82.00
REAR BUMPER REINFORCEMENT <i>Distorted</i>	1	456.50	✓ 456.50
REAR BUMPER REVERSE SENSOR <i>1 piece damaged</i>	2	498.90	498.90 ✓ 997.80
REAR BUMPER REVERSE SENSOR 'O' RING <i>1 piece new</i>	2	25.00	25 50.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	2	25.50	+ 51.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAI ENG KEAT
30 TANAH MERAH KECHIL RD #07-09
SINGAPORE 465558

Contact : 96730759

TAX INVOICE

Repair Code : CLM16394

Date in : 16/08/2024

Vehicle Num. : SNH8723L

Model : TOYOTA CAMRY HYBRID 4DR SEDAN (AT) ELEGANCE

Chassis/Eng# : JTNB23HK003116383/A25A5720602

REAR BUMPER SIDE RETAINER L/R	2	185.50	371.00
REAR BUMPER SPONGE	1	121.90	121.90
REAR END PANEL	1	983.20	983.20
REAR END PANEL ANTENNA SENSOR	1	452.30	452.30
REAR END PANEL INNER TOP GARNISH	1	314.20	314.20
REAR TAILLAMP L/R	2	1331.80	2663.60
REAR TAILLAMP LOWER COVER L/R	2	89.90	179.80
Subtotal before discount			13,807.90
Percentage discount 25%			3,451.98
Sub-total 1			10,355.93
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET	1	30.00	30.00
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
REAR TAILLAMP CLIPS L/R - SET	2	20.00	40.00
Subtotal before discount			150.00
Percentage discount 0%			0.00
Sub-total 2			150.00
Parts-total			10,505.93

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
21 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LAI ENG KEAT
30 TANAH MERAH KECHIL RD #07-09
SINGAPORE 465558

Contact : 96730759

TAX INVOICE

Repair Code : CLM16394
Date in : 16/08/2024
Vehicle Num. : SNH8723L
Model : TOYOTA CAMRY HYBRID 4DR SEDAN (AT) ELEGANCE
Chassis/Eng# : JTNB23HK003116383/A25A5720602

LABOUR

To transfer rear bootlid mechanism lock outer handle reflector
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.

1700

✓ 80.00
✓ 80.00
60 100.00
700 1,200.00
700 1,000.00
80 120.00

Labour Total


2,580.00

Parts & Labour Total

13,085.93

*** This is a computer-generated document which requires no signature.***

page 3



Adrian Cij
2/8 19/08/24

no of days: 06 days

Supplementary: 284.70

total: 6985.20

C/S: S.B.K

S.B.K

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

LAI ENG KEAT

30 TANAH MERAH KECHIL RD

#07-09

SINGAPORE 465558

Repair Code: CLM16394

Date in: 16/08/2024

Vehicle No.: SNH8723L

Model: TOYOTA CAMRY HYBRID 4DR SEDAN (AT) ELEGANCE

Chassis/Eng#: JTNB23HK003116383/A25A5720602

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	REAR EXHAUST SILENCER BOX	L	1	\$ 1,578.20	\$ 1,578.20
2	REAR EXHAUST GASKET	L	1	\$ 44.40	\$ 44.40
3	REAR EXHAUST RUBBER MOOUNTING	L	1	\$ 66.80	\$ 66.80
4	REAR LH FENDER INNER TRIM GARNISH	L	1	\$ 699.50	\$ 699.50
5	REAR LH BLIND SPOT MODULE	L	1	\$ 2,174.60	\$ 2,174.60
6	REAR LH BLIND SPOT MODULE WIRE HARNESS	L	1	\$ 379.60	\$ 379.60
	Sub total before discount:				\$ 4,943.10
	Percentage discount 25%:				\$ 1,235.78
	Sub-total 1 :				\$ 3,707.33
	Parts Total:				\$ 3,707.33

Adnan
w/s 20/08/24

379.60

284 70