



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION FOR

NAME:

COMPANY NAME: India International Insurance Pte Ltd

STREET ADDRESS: 64 Cecil Street, #04/#05-02, IOB Building Singapore

POSTAL CODE: 49711

PHONE: 6347 6100

QUOTATION

DATE: 16/08/2024

REF: SV0Q248E0002

VEHICLE NO: SLU6623K

MAKE: BMW

MODEL: 116d

PREPARED BY: RANDELL GOON

Not Authorized
in focus
20/8/24 @ 10.45am
2 days.
2/s \$2000

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
<u>LABOUR</u>							
1	TO REMOVE & REPLACE REAR BUMPER, REAR LAMP LH [OUTER], REAR LAMP RH [OUTER] & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$400.00	\$ 400.00	200	\$ 400.00
2	TO SPRAY REAR BUMPER, BUMPER REINFORCEMENT REAR & REAR PANEL	1		\$500.00	\$ 500.00	300	\$ 500.00
3	TO REPLACE/TRANSFER THE REAR BUMPER SENSORS, REVERSE CAMERA & OTHER PARTS	1		\$200.00	\$ 200.00	30	\$ 200.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$150.00	\$ 150.00	20	\$ 150.00
5	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$200.00	\$ 200.00	11X	\$ 200.00
6	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$150.00	\$ 150.00	11X	\$ 150.00
7	SUNDRIES	1		\$50.00	\$ 50.00	11X	\$ 50.00
<u>PARTS</u>							
1	BUMPER REAR COVER	1		\$820.00	\$ 820.00	20/20	\$ 820.00
2	BUMPER BRACKET REAR LH	1		\$150.00	\$ 150.00	11	\$ 150.00
3	BUMPER BRACKET REAR RH	1		\$150.00	\$ 150.00	11	\$ 150.00
4	BUMPER CLIPS	10		\$2.00	\$ 20.00	11	\$ 20.00
5	TOW EYE COVER REAR RH	1		\$52.00	\$ 52.00	11	\$ 52.00
6	REVERSE CAMERA	1		\$795.00	\$ 795.00	11	\$ 795.00
7	NUMBER PLATE	1		\$45.00	\$ 45.00	20	\$ 45.00
8	NUMBER PLATE HOLDER	1		\$40.00	\$ 40.00	11	\$ 40.00
9	REAR PANEL	1		\$500.00	\$ 500.00	11	\$ 500.00
10	BUMPER REAR REINFORCEMENT	1		\$330.00	\$ 330.00	11	\$ 330.00

5.2

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
11	NUMBER PLATE LAMP REAR	2		\$20.00	\$ 40.00	74X	\$ 40.00
12	SENSOR BRACKET REAR (4PCS/SET)	1		\$39.00	\$ 39.00	54X	\$ 39.00
13	SENSOR BUMPER REAR	4		\$50.00	\$ 200.00	11X	\$ 200.00
14	TAILGATE LOCK	1		\$250.00	\$ 250.00	11X	\$ 250.00
15	REAR LAMP LH [OUTER]	1		\$340.00	\$ 340.00	11X	\$ 340.00
16	REAR LAMP RH [OUTER]	1		\$340.00	\$ 340.00	11X	\$ 340.00
SUBTOTAL					\$ 5,761.00	SUBTOTAL	\$ 5,761.00
GST 9%					\$ 518.49	GST 9%	\$ 518.49
TOTAL					\$ 6,279.49	TOTAL	\$ 6,279.49

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 217
52
1916.15
530
40
2576.15
205
2004