



**DICKSON GROUP**  
Your Trusted Automotive Solutionist

**DICKSON AUTO CARE CENTRE PTE LTD**  
29 UBI ROAD 4, DICKSON AUTO CENTRE  
SINGAPORE 408619  
TEL: 6668 1122 | FAX: 6668 1123

## QUOTATION

### QUOTATION FOR

**NAME:**  
**COMPANY NAME:** India International Insurance Pte Ltd  
**STREET ADDRESS:** 64 Cecil Street, #04/#05-02, IOB Building Singapore  
**POSTAL CODE:** 49711  
**PHONE:** 6347 6100

**DATE:** 16/08/2024

**REF:** SV0Q248E0002

**VEHICLE NO:** SLU6623K

**MAKE:** BMW

**MODEL:** 116d

**PREPARED BY:** RANDELL GOON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<b><u>LABOUR</u></b>						
1	TO REMOVE & REPLACE REAR BUMPER, REAR LAMP LH [OUTER], REAR LAMP RH [OUTER] & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$400.00	\$ 400.00		\$ 400.00
2	TO SPRAY REAR BUMPER, BUMPER REINFORCEMENT REAR & REAR PANEL	1		\$500.00	\$ 500.00		\$ 500.00
3	TO REPLACE/TRANSFER THE REAR BUMPER SENSORS, REVERSE CAMERA & OTHER PARTS	1		\$200.00	\$ 200.00		\$ 200.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$150.00	\$ 150.00		\$ 150.00
5	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$200.00	\$ 200.00		\$ 200.00
6	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$150.00	\$ 150.00		\$ 150.00
7	SUNDRIES	1		\$50.00	\$ 50.00		\$ 50.00
	<b><u>PARTS</u></b>						
1	BUMPER REAR COVER	1		\$820.00	\$ 820.00		\$ 820.00
2	BUMPER BRACKET REAR LH	1		\$150.00	\$ 150.00		\$ 150.00
3	BUMPER BRACKET REAR RH	1		\$150.00	\$ 150.00		\$ 150.00
4	BUMPER CLIPS	10		\$2.00	\$ 20.00		\$ 20.00
5	TOW EYE COVER REAR RH	1		\$52.00	\$ 52.00		\$ 52.00
6	REVERSE CAMERA	1		\$795.00	\$ 795.00		\$ 795.00
7	NUMBER PLATE	1		\$45.00	\$ 45.00		\$ 45.00
8	NUMBER PLATE HOLDER	1		\$40.00	\$ 40.00		\$ 40.00
9	REAR PANEL	1		\$500.00	\$ 500.00		\$ 500.00
10	BUMPER REAR REINFORCEMENT	1		\$330.00	\$ 330.00		\$ 330.00

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
11	NUMBER PLATE LAMP REAR	2		\$20.00	\$ 40.00		\$ 40.00
12	SENSOR BRACKET REAR (4PCS/SET)	1		\$39.00	\$ 39.00		\$ 39.00
13	SENSOR BUMPER REAR	4		\$50.00	\$ 200.00		\$ 200.00
14	TAILGATE LOCK	1		\$250.00	\$ 250.00		\$ 250.00
15	REAR LAMP LH [OUTER]	1		\$340.00	\$ 340.00		\$ 340.00
16	REAR LAMP RH [OUTER]	1		\$340.00	\$ 340.00		\$ 340.00
<b>REMARKS:</b>					<b>SUBTOTAL</b>	\$ 5,761.00	<b>SUBTOTAL</b> \$ 5,761.00
					<b>GST 9%</b>	\$ 518.49	<b>GST 9%</b> \$ 518.49
					<b>TOTAL</b>	\$ 6,279.49	<b>TOTAL</b> \$ 6,279.49

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND  
COMPANY STAMP)

(AUTHORISED SIGNATURE)

