



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION

INCIDENT NO.: /20240816/0589

FIRE REPORTED ON: 16 August 2024

TIME OF CALL: 13:04:34 hrs

STATION

COVERAGE: Ang Mo Kio Fire Station

LOCATION OF FIRE:

At the traffic light junction

Along Ang Mo Kio Avenue 1 & Ang Mo Kio Avenue 2
Singapore

2. INCIDENT INFORMATION

FIRE INVOLVED: The engine compartment of a Hyundai (SLA3862L) car.

METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel jet and a hose line water jet from fire appliances.

PROBABLE CAUSE OF FIRE: Accidental (Overheating of the engine compartment)

DAMAGE OBSERVED*: As a result of the fire, the engine compartment of the car was damaged. Other parts of the car sustained varying degrees of heat, smoke and water damage.

The nearby traffic island and a lamp post sustained varying degrees of heat, smoke, and water damage.

3. FATALITY/INJURY INFORMATION

NAME

NRIC/FIN

DEAD/INJURIES SUSTAINED

NIL

NIL

NIL

REPORT ISSUED BY:

ANG LI FENG

for COMMISSIONER

SINGAPORE CIVIL DEFENCE FORCE

**This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.*

This is a computer generated report. No signature is required.