

(08/11/13) Wef
ASS. REC. BY:

REF:

CD / FCI 24080283 / Xma³


0005

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SCH 8921L
at Workshop m/s CYCLE & CARRIAGE
of 188, PANDAN LAMP
Insured: FCI
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SCH 8921L Yr Regn: 2024 1MAY
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: MERCEDES BENZ C200 AVX LN cc 1997
Colour: GREEN A/C: Insured / Std / NI / NA
Sp. Reading: 6285 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: W1K2140502A 043016
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 275/40R19
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / WIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>13/08/24</u>		D.O.I. <u>02/09/24</u>
Survey held at <u>PANDAN L</u>		

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐
☐

: Prel. Report

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐
☐
☐
☐

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

) : S + RS \$ _____

) : Photos

) : Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Drop-off
Sunday night
Away for 5 weeks
Parts/



Mercedes-Benz

15/08
23/08

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCH8921L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information
WIP No 20129
Reg No/Reg Date SCH8921L / 20/05/2024
Date In/Mileage
Chassis No W1K2140502A0430161
Engine No 254920V0542022
Make/Model MB/E 200 SEDAN
Colour/Trim 021 188 Verde Silve/ 041 104 ARTICO Tonk

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	15/08/2024/ 18:19		1208/ Foong Shiuh Jye

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
THIS IS NOT AN OFFICIAL TAX INVOICE				
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 7240080533 // 13 AUG 2024 DRIVE IN/TP : 14 AUG 2024 // SW555E-FIRST CAP DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES RESPRAY BUMPER REAR				
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO			0.10	
M BPNSUN SUNDRIES				
M TRIM, BUMPER	1.00	2224.71	00.00	2224.71
M BUMPER REAR LOWER	1.00	445.10	00.00	445.10
M BUMPER REAR CHROME	1.00	158.83	00.00	158.83
M BASIC CARRIER, BUMPER	1.00	83.12	00.00	83.12

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Foong Shiuh Jye
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4346 HP: 97896038 Fax: 6872 1272
Email: shiuhjye.foong@cyclecarriage.com.sg

Confirmed & accepted by
Acknowledged by Repairer

Signature:
Date:

Nett 5,706.76
9% GST on 5706.76 513.61
Total Payable 6,220.37

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	000E
Vehicle Details	
Vehicle No.:	SCH8921L
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Sep 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 AVG LN IRG
Primary Colour:	Silver
Manufacturing Year:	2024
Engine No.:	254920V0542022
Chassis No.:	W1K2140502A043016
Maximum Power Output:	167.0 kW (223 bhp)
Open Market Value:	\$62,544.00
Original Registration Date:	20 May 2024
First Registration Date:	20 May 2024
Transfer Count:	0
Actual ARF Paid:	\$92,360.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 May 2034
PARF Rebate Amount:	\$60,000.00
Intended COE Rebate Details	
COE Expiry Date:	19 May 2034
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$102,338.00
COE Rebate Amount:	\$99,366.00
Total Rebate Amount:	\$159,366.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 03 Sep 2024

OK



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SCH8921L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

20129

SCH8921L / 20/05/2024

02/09/2024/ 6285

W1K2140502A0430161

254920V0542022

MB/E 200 SEDAN

021 188 Verde Silve/ 041 104 ARTICO Tonk

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	04/07/2025/ 16:52	SJ	1208/ Foong Shiuh Jye				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : 7240080533 // 13 AUG 2024								
DRIVE IN/TP : 14 AUG 2024 // SCH555E-FIRST CAP								
DATE IN/DATE SURVEY: 02 SEP 2024 // LKK RASUL								
BY/AUTHORIZED ON : 23 AUG 2024 // LKK DAPHNE LEE								
A BPILAB								
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								
RESPRAY BUMPER REAR							0.05	800.00 /
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO							0.10	380.00 /
M BPNSUN								
SUNDRIES								
X TRIM, BUMPER / DD								
X BUMPER REAR LOWER / Cut								
X BUMPER REAR CHROME / Cut								
X TRIM STRIP / Cut supp								
					1.00	2224.71	00.00	2224.71
					1.00	445.10	00.00	445.10
					1.00	158.83	00.00	158.83
					1.00	184.02	00.00	184.02

Confirmed & accepted by

9% GST on **Nett** 5,167.66 **5,167.66**
465.09

Authorized signatory and company stamp

Total Payable **5,632.75**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

ESTIMATE FOR SCH8921L

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information
WIP No 20129
Reg No/Reg Date SCH8921L / 20/05/2024
Date In/Mileage 02/09/2024/ 6285
Chassis No W1K2140502A0430161
Engine No 254920V0542022
Make/Model MB/E 200 SEDAN
Colour/Trim 021 188 Verde Silve/ 041 104 ARTICO Tonk

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	04/07/2025/ 16:52	SJ	1208/ Foong Shiuh Jye

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X TRIM STRIP	1.00	184.02	00.00	184.02

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Confirmed & accepted by

	Nett	184.02
9% GST on	184.02	16.56

Authorized signatory and company stamp

Total Payable 200.58

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg