



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2600612
3 ANSON ROAD #16-00	INV Date	26/01/2026
SPRINGLEAF TOWER	Reference	CD/CTI24080287/Apa3q2
SINGAPORE 079909	Code	CTI
ATTN: ALFRED TOH		

PROFESSIONAL SERVICE FEE

Vehicle No.	SNG 6516L
Insured Veh.	XE 9131K
Claim No.	SNM24D204643/C02
Policy No.	DMCVSNA00021652401
Accident Date	15/08/2024
Inspection Date	20/09/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN: ALFRED TOH		Ref: CD/CTI24080287/Apa3q2(N) Date: 26/01/2026 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 9131K	Veh. Inspected	SNG 6516L
Policy No.	DMCVSNA00021652401	Coverage (\$)	0.00
Claim No.	SNM24D204643/C02	Excess (\$)	0.00
Assign From	ALFRED TOH	Assign Date	20/09/2024
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WDC1569422J688432	Colour	BLACK
Odometer	88532 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	MICHELIN	6 mm
L/H Front Tyre	235/50 R18	MICHELIN	6 mm
R/H Rear Tyre	235/50 R18	MICHELIN	6 mm
L/H Rear Tyre	235/50 R18	MICHELIN	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	15/08/2024	Inspection Date	20/09/2024
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 6516L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER RH	DENTED	3,360.00	2,855.00
1	REAR RH FENDER COWLING	NOT NECESSARY	346.00	-
1	BOOT LID RUBBER	NOT NECESSARY	297.00	-
1	REAR RH FENDER WHEEL ARCH GARNISH	CUT	382.00	260.00
1	TAIL LAMP RH	CRACKED	1,160.00	910.00
1	TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	345.00	-
1	TAIL LAMP LOWER RETAINER RH	NOT NECESSARY	121.00	-
1	REAR BUMPER	DEFORMED	1,667.00	1,416.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	799.00	-
1	REAR BUMPER SIDE RETAINER RH	CRACKED	101.00	101.00
1	REAR LOWER BUMPER	CUT	1,235.00	650.00
3	REVERSE SENSOR @\$297.00	DAMAGED (1 PCS ONLY)	891.00	297.00
1	REAR BUMPER CENTRE TOP CHROME	NECESSARY	473.00	298.00
	LESS 10% DISCOUNT		-1,117.70	-678.70
			10,059.30	6,108.30
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR RH FENDER COWLING CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET REAR FENDER INNER TRIM CLIPS RH (SN)	NOT NECESSARY	40.00	-
1	SET REAR RH FENDER WHEEL ARCH GARNISH CLIPS (SN)	NECESSARY	40.00	20.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR SPORTS RIM RH (SN)	CUT	1,200.00	1,000.00
			1,380.00	1,050.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	30.00
	TO REMOVE AND REFIT REVERSE SENSOR .		80.00	50.00
	TO REMOVE AND REFIT INNER TRIM .		100.00	80.00
	TO REMOVE AND REFIT SEAT CUSHION .	NOT NECESSARY	250.00	-
	TO SPRAY ANTI RUST .		100.00	60.00

Report Ref No. CD/CTI24080287/Apa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WHEEL ALIGNMENT.		120.00	80.00
	(REAR) TO SPRAY PAINTING.		1,000.00	600.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS.INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL RH .		1,600.00	700.00
			3,300.00	1,600.00
	GRAND TOTAL		14,739.30	8,758.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00

Report Ref No. CD/CTI24080287/Apa3q2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 7)


PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L



PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 6516L

