

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883

TEL: 6747 7636 FAX: 6748 5071

Email: kangcar@singnet.com.sg

GST REG NO: 201300201N

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Tel: 63896111

Fax: 62247175

Attn: Motor Claim Department

Your Ref No: XE9131K

Claim Type: Third Party

Accident Date: 15 August 2024

TP Veh Reg No: XE9131K

Estimate No: EST2400371

Date: 20 Sep 2024

Policy No: 5142816809

Veh Reg No: SNG6516L

Make/Model: MERCEDES BEN
GLA180 URBAN (R18
LED)

Chassis No: WDC1569422J688432

Engine No: 27091031947396

Reg. Date: 07 Feb 2020

Estimate Repair Cost to Vehicle No: SNG6516L

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR FENDER RH <i>Dented</i>	3,360.00	1 PC	3,360.00 ✓	2855
2 REAR RH FENDER COWLING <i>new</i>	346.00	1 PC	346.00 X	
3 BOOT LID RUBBER <i>new</i>	297.00	1 PC	297.00 X	
4 REAR RH FENDER WHEEL ARCH GARNISH <i>cut</i>	382.00	1 PC	382.00 ✓	260
5 TAIL LAMP - RH <i>cut</i>	1,160.00	1 PC	1,160.00 ✓	910
6 TAIL LAMP PANEL RH <i>Regis</i>	345.00	1 PC	345.00 X	
7 TAIL LAMP LOWER RETAINER RH <i>new</i>	121.00	1 PC	121.00 X	
8 REAR BUMPER <i>Debond</i>	1,667.00	1 PC	1,667.00 ✓	1416
9 REAR BUMPER REINFORCEMENT <i>new</i>	799.00	1 PC	799.00 X	
10 REAR BUMPER SIDE RETAINER RH <i>new</i>	101.00	1 PC	101.00 X	
11 REAR LOWER BUMPER <i>cut</i>	1,235.00	1 PC	1,235.00 ✓	650
12 REVERSE SENSORS <i>3 piece dng</i>	297.00	3 PCS	891.00 ✓	297
13 REAR BUMPER CENTRE TOP CHROME <i>new</i>	473.00	1 PC	473.00 ✓	298
			11,177.00	
		Less 10%	-1,117.70	10,059.30

Special Net				
14 REAR RH FENDER COWLING CLIPS <i>new</i>	40.00	1 SET	40.00 X	
15 REAR FENDER INNER TRIM CLIPS RH <i>new</i>	40.00	1 SET	40.00 X	
16 REAR RH FENDER WHEEL ARCH GARNISH CLIPS <i>new</i>	40.00	1 SET	40.00 X	1050
17 REAR BUMPER CLIPS <i>new</i>	60.00	1 SET	60.00 X	30
18 REAR SPORTS RIM RH <i>cut</i>	1,200.00	1 PC	1,200.00 ✓	1000
				1,380.00

Labour				
19 TO CHECK WIRING	50.00	1	50.00 ✓	30
20 TO REMOVE AND REFIT INNER TRIM	100.00	1	100.00 X	80
21 TO REMOVE AND REFIT REVERSE SENSOR	80.00	1	80.00 X	50
22 TO REMOVE AND REFIT SEAT CUSHION	250.00	1	250.00 X	
23 TO SPRAY ANTI RUST	100.00	1	100.00 X	20
24 TO CHECK WHEEL ALIGNMENT	120.00	1	120.00 X	80
25 (REAR) TO SPRAY PAINTING	1,000.00	1	1,000.00 X	600
26 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00	1	1,600.00 ✓	700
				3,300.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883

TEL: 6747 7636 FAX: 6748 5071

Email: kangcar@singnet.com.sg

GST REG NO: 201300201N

Total	14,739.30
Add GST @ 9%	1,326.54
Total Amount Payable SGD	16,065.84

SINGAPORE DOLLAR SIXTEEN THOUSAND SIXTY FIVE AND CENTS EIGHTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

Admining.

2/s 20/09/24

05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 8758.30

2/s: 7k

7k

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE