



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SEVAM S/O A KUMARASAMY
BLK 8 ST GEORGE'S LANE #02-245
SINGAPORE 320008

TAX INVOICE

TP 1st Cap
Hui Rong

Repair Code : CLM18340

Date in : 16/08/2024

Vehicle Num. : SNJ9542A

Model : MERCEDES BENZ E200 SEDAN (R18)

Chassis/Eng# : WDD2120342A791948/27492030057422

Contact : 91055750

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID '7G-TRONIC' EMBLEM <i>24</i>	1	97.00	✓ 97.00
REAR BOOTLID 'C&C' EMBLEM <i>2</i>	1	88.00	✓ 88.00
REAR BOOTLID 'E200' EMBLEM <i>per</i>	1	89.00	✓ 89.00
REAR BOOTLID 'LOGO' EMBLEM	1	91.00	✓ 91.00
REAR BOOTLID 'LOGO' EMBLEM CLIPS <i>new</i>	3	8.00	+ 24.00
REAR BOOTLID (ALUMINIUM) <i>Repr</i>	1	2450.00	+ 2,450.00
REAR BOOTLID MECHANISM LOCK <i>3000</i>	1	496.00	+ 496.00
REAR BOOTLID WEATHER STRIP	1	245.00	+ 245.00
REAR BUMPER <i>Delnd</i>	1	1789.00	✓ 1,789.00
REAR BUMPER EXHAUST CHROME TAIL L/R <i>R17 Delnd</i>	2	358.00	358 716.00
REAR BUMPER INNER CENTER BRACKET <i>Carld</i>	1	215.00	✓ 215.00
REAR BUMPER LOWER BRACKET L/R <i>Carld</i>	2	98.00	✓ 196.00
REAR BUMPER LOWER LID <i>Delnd</i>	1	415.00	✓ 415.00
REAR BUMPER LOWER LID CHROME MOULDING <i>LT</i>	1	298.00	✓ 298.00
REAR BUMPER REINFORCEMENT <i>new</i>	1	799.00	+ 799.00
REAR BUMPER REVERSE SENSOR <i>2 pieces new</i>	4	198.00	356 792.00
REAR BUMPER REVERSE SENSOR 'O' RING <i>2 pieces new</i>	4	20.00	40 80.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	20.00	✓ 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SEVAM S/O A KUMARASAMY
BLK 8 ST GEORGE'S LANE #02-245
SINGAPORE 320008

TAX INVOICE

Repair Code : CLM18340

Date in : 16/08/2024

Vehicle Num. : SNJ9542A

Model : MERCEDES BENZ E200 SEDAN (R18)

Chassis/Eng# : WDD2120342A791948/27492030057422

Contact : 91055750

REAR BUMPER REVERSE SENSOR WIRE HARNESS	3pc in	1	305.00	+	305.00
REAR BUMPER SIDE RETAINER L/R		2	4267 105.00	+	210.00
REAR BUMPER TOW HOOK COVER	Delivered	1	75.00	✓	75.00
REAR END PANEL	Repair	1	3840.30 869.00	+	869.00
REAR TAILLAMP L/R	AC in	2	980.00	+	1,960.00
Subtotal before discount					12,379.00
Percentage discount 10%					1,237.90
Sub-total 1					11,141.10
REAR BUMPER CLIPS - SET	3pc	1	80.00	30	80.00
REAR BUMPER RIVET - SET		1	100.00	50	100.00
Subtotal before discount					180.00
Percentage discount 0%					0.00
Sub-total 2					180.00
Parts-total					11,321.10

LABOUR

To reset system after repair works	400.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	50 80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800 1,000.00

*** This is a computer-generated document which requires no signature.***



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SEVAM S/O A KUMARASAMY
BLK 8 ST GEORGE'S LANE #02-245
SINGAPORE 320008

TAX INVOICE

Repair Code : CLM18340

Date in : 16/08/2024

Vehicle Num. : SNJ9542A

Model : MERCEDES BENZ E200 SEDAN (R18)

Chassis/Eng# : WDD2120342A791948/27492030057422

Contact : 91055750

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,700.00
Parts & Labour Total	14,021.10

980

3W 1,000.00
30 120.00

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Lim
n/s 19/08/24
04.24p-

total: 4900.30

L/S: 3.9K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: