

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To In: _____ Vehicle No: _____

at W: _____ m/s

of _____

Insured: _____

Policy: _____

Claims: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNJ9542A Yr Regn: 2013, Oct

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E200 C.D. 1991

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 63869 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120342A791948

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Tourador

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 19/08/24

Survey held at

451

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap

COE Expiry: 30/06/2033

Estimate given during: Yes (✓)

1st Survey: No ()

MV: 150K

PV: 103.8K

Nett: 46.2K

1347

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

1)

Date/Time, File Return to?

☐ : Final Report

Transportation: _____

2)

Add Fee: ☐ : Site Insp (\$

3 + RS \$)

☐ : Interview (\$

Photos

☐ : Tech. Insp (\$

Others

Report Format: _____



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SEVAM S/O A KUMARASAMY
BLK 8 ST GEORGE'S LANE #02-245
SINGAPORE 320008

TAX INVOICE

Repair Code : CLM18340

Date in : 16/08/2024

Vehicle Num. : SNJ9542A

Model : MERCEDES BENZ E200 SEDAN (R18)

Chassis/Eng# : WDD2120342A791948/27492030057422

Contact : 91055750

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID '7G-TRONIC' EMBLEM <i>new</i>	1	97.00	✓ 97.00
REAR BOOTLID 'C&C' EMBLEM <i>2</i>	1	88.00	✓ 88.00
REAR BOOTLID 'E200' EMBLEM <i>new</i>	1	89.00	✓ 89.00
REAR BOOTLID 'LOGO' EMBLEM	1	91.00	✓ 91.00
REAR BOOTLID 'LOGO' EMBLEM CLIPS <i>new</i>	3	8.00	+ 24.00
REAR BOOTLID (ALUMINIUM) <i>Repair</i>	1	2450.00	+ 2,450.00
REAR BOOTLID MECHANISM LOCK <i>3</i>	1	496.00	+ 496.00
REAR BOOTLID WEATHER STRIP <i>3</i>	1	245.00	+ 245.00
REAR BUMPER <i>Delend</i>	1	1789.00	✓ 1,789.00
REAR BUMPER EXHAUST CHROME TAIL L/R <i>RT1 Delend</i>	2	358.00	358 716.00
REAR BUMPER INNER CENTER BRACKET <i>curled</i>	1	215.00	✓ 215.00
REAR BUMPER LOWER BRACKET L/R <i>curled</i>	2	98.00	✓ 196.00
REAR BUMPER LOWER LID <i>Delend</i>	1	415.00	✓ 415.00
REAR BUMPER LOWER LID CHROME MOULDING <i>LT</i>	1	298.00	✓ 298.00
REAR BUMPER REINFORCEMENT <i>new</i>	1	799.00	+ 799.00
REAR BUMPER REVERSE SENSOR <i>2 pieces new</i>	4	198.00	356 792.00
REAR BUMPER REVERSE SENSOR 'O' RING <i>2 pieces new</i>	4	20.00	40 80.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	20.00	✓ 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SEVAM S/O A KUMARASAMY
 BLK 8 ST GEORGE'S LANE #02-245
 SINGAPORE 320008

TAX INVOICE

Repair Code : CLM18340

Date in : 16/08/2024

Vehicle Num. : SNJ9542A

Model : MERCEDES BENZ E200 SEDAN (R18)

Chassis/Eng# : WDD2120342A791948/27492030057422

Contact : 91055750

REAR BUMPER REVERSE SENSOR WIRE HARNESS	305.00	+	305.00
REAR BUMPER SIDE RETAINER L/R	210.00	+	210.00
REAR BUMPER TOW HOOK COVER	75.00	✓	75.00
REAR END PANEL	869.00	+	869.00
REAR TAILLAMP L/R	980.00	+	1,960.00
Subtotal before discount			12,379.00
Percentage discount 10%			1,237.90
Sub-total 1			11,141.10
REAR BUMPER CLIPS - SET	80.00	30	80.00
REAR BUMPER RIVET - SET	100.00	50	100.00
Subtotal before discount			180.00
Percentage discount 0%			0.00
Sub-total 2			180.00
Parts-total			11,321.10

LABOUR

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

400.00
 50 80.00
 100.00
 800 1,000.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SEVAM S/O A KUMARASAMY
BLK 8 ST GEORGE'S LANE #02-245
SINGAPORE 320008

TAX INVOICE

Repair Code : CLM18340

Date in : 16/08/2024

Vehicle Num. : SNJ9542A

Model : MERCEDES BENZ E200 SEDAN (R18)

Chassis/Eng# : WDD2120342A791948/27492030057422

Contact : 91055750

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

3w 1,000.00
30 120.00

Labour Total

2,700.00

Parts & Labour Total

14,021.10

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Lim
n/s 19/08/24
04.24p-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: