



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMF 6102P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TORN	\$688.50	\$688.50
1	REAR BUMPER SIDE HOLDER	CRACKED	\$25.90	\$25.90
1	TAILLAMP	NOT NECESSARY	\$279.70	\$0.00
1	TAILLAMP PANEL	TO REPAIR SEE LABOUR	\$214.60	\$0.00
1	TAILLAMP LOWER BRACKET	NOT NECESSARY	\$45.50	\$0.00
1	REAR FENDER	DENTED	\$989.90	\$989.90
1	REAR WINDSCREEN MOULDING	NECESSARY	\$185.20	\$185.20
	LESS 20.00% DISCOUNT		(\$485.86)	(\$377.90)
			\$1,943.44	\$1,511.60

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	REAR FENDER SEALANT (SN)	NECESSARY	\$60.00	\$60.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$60.00	\$60.00
			\$170.00	\$150.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL.		\$1,000.00	\$600.00
	SPRAY PAINTING TO AFFECTED AREA		\$600.00	\$500.00
	WIRING CHECK		\$50.00	\$30.00
	TO SPRAY TUFF COAT		\$100.00	\$60.00
	TO REMOVE REVERSE SENSOR		\$100.00	\$50.00
	TO REMOVE UPHOLSTERY		\$150.00	\$40.00
	TO REMOVE REAR WINDSCREEN		\$180.00	\$120.00
			\$2,180.00	\$1,400.00

GRAND TOTAL		\$4,293.44	\$3,061.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,400.00
Report Ref No: CS/INC24060112/Anh3e2			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

TOTAL FOR SPARE PARTS: \$ 2,113.44 \$ 1,661.60
TOTAL FOR LABOUR : \$ 2,180.00 \$ 1,400.00
TOTAL REPAIR COST: \$ 4,293.44 \$ 3,061.60

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.