

ONE GARAGE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT
SINGAPORE 415875
TEL: 96311088

TO	: NTUC	DATE	: 19/6/2024
VEHICLE NO	: SMF6102P (2009)	Hui Rong	
VEHICLE MODEL	: HONDA CIVIC		
CHASSIS NO	: JHMFD46209S200457		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>ton</i>	1	\$ 688.50	\$ 688.50
2	REAR BUMPER SIDE HOLDER <i>cut</i>	1	\$ 25.90	\$ 25.90
3	TAILLAMP <i>new</i>	1	\$ 279.70	\$ 279.70
4	TAILLAMP PANEL <i>new</i>	1	\$ 214.60	\$ 214.60
5	TAILLAMP LOWER BRACKET <i>new</i>	1	\$ 45.50	\$ 45.50
6	REAR FENDER <i>Derbed</i>	1	\$ 989.90	\$ 989.90
7	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 185.20	\$ 185.20

1889.50
1511.60

TOTAL PRICE: \$ 2,429.30
LESS 20% \$ 485.86
SUB TOTAL PRICE: \$ 1,943.44

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR FENDER SEALANT <i>3pr</i>	1	\$ 60.00	\$ 60.00
3	REAR WINDSCREEN SEALANT	1	\$ 60.00	\$ 60.00

TOTAL : \$ 170.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>600</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 600.00	<i>500</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO SPRAY TUFF COAT	\$ 100.00	<i>60</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
	TO REMOVE UPHOLSTERY	\$ 150.00	<i>40</i>	
6	TO REMOVE REAR WINDSCREEN	\$ 180.00	<i>120</i>	

TOTAL: \$ 2,180.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 2,113.44

TOTAL LABOUR COST: \$ 2,180.00

TOTAL REPAIR COST: \$ 4,293.44

CRK Auto Consultants hence notify the Repairer of the following:
Resurvey before/after spray painting \$

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3061.60

4/s: 2.HK

04 days