

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24080292/RPA3Q2**Date:** 05/12/2024REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0006316  
**Claimant Vehicle No :** SKZ5644S **Insured Vehicle No :** SND6509Z  
 Date of Loss: 14/08/2024 Nature of Claim: TP Claim No: MFL2024D0009479

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ5644S**  
 Make & Model: NISSAN X-TRAIL, 2.0 CVT ABS 4WD S/R 7-STR (A) Engine No: MR20814319B  
 Reg. Date: 27/01/2016 (Man. Year: 2015) Chassis No: JN1JANT32Z0001383  
 Colour: Red Odometer: 108742 km  
 Engine Capacity: 1997 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18  
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,369.92	1,181.28	1,188.64	50.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,925.00	2,420.00	505.00	17.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,294.92</b>	<b>3,601.28</b>	<b>1,693.64</b>	<b>31.99</b>
<b>+ GST 9.00/9.00% (S\$)</b>	476.54	324.12	152.42	31.98
<b>Nett Amount (S\$)</b>	<b>5,771.46</b>	<b>3,925.40</b>	<b>1,846.06</b>	<b>31.99</b>
<b>+ Car Rental (3.0 x S\$150.00/day + 9.00% GST) (S\$)</b>		490.50		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>4,418.08</b>		

INSPECTION

Date of Assignment: 27/08/2024  
 Date Inspected: 27/08/2024 Inspected At: Tan Chong Motor Sales Pte Ltd (HQ)  
 913 Bukit Timah Road  
 Singapore 589623  
 Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2024)
Parts:	M1-SUV	NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ5644S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SENSOR-REVERSE	Shorted	250.00 FS	*250.00 FS
2	1		*REAR LICENCE PLATE	Scratched	60.00 FS	*60.00 FS
3	1		*FACE-RR BUMPER	Torn	849.00 FN	*849.00 FN
4	2		*GROMMET	Necessary	4.40 FS	*4.40 FS
5	10		*CLIP	Necessary	15.00 FN	*15.00 FN
6	1		*FINISHER	Not Necessary	131.00 FN	*- FN
7	1		*BRACKET-BUMP LH	Not Necessary	43.20 FN	*- FN
8	1		*BRACKET-BUMP RH	Not Necessary	43.30 FN	*- FN
9	1		*REINF-BUMPER RR	Not Necessary	663.20 FN	*- FN
10	1		*STAY-RH BUMPER	Not Necessary	217.90 FN	*- FN
11	1		*STAY-LH BUMPER	Not Necessary	217.90 FN	*- FN
12	1		*WEATHER STRIP	Not Necessary	156.80 FN	*- FN
13	1		*EMBLEM	Necessary	72.20 FN	*72.20 FN
14	1		*EMBLEM	Necessary	122.40 FN	*122.40 FN
15	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
						F=Franchise part. S=SpcNett. N=NettItemDisc.
					Sub Total (\$\$)	2,876.30 1,393.00
					- Nett Item Discount on N Items 20.00/20.00% (\$\$)	506.38 211.72
					Total Parts (\$\$)	2,369.92 1,181.28

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	120.00
2	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	New	110.00	110.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	100.00	0.00
4	REPAIR RR ENO PANEL, TAILGATE RENEW RR BUMPER	New	1,075.00	860.00
5	S/PAINT RR BUMPER( 2TONE),RR ENO PANEL & TAILGATE	New	1,520.00	1,330.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,925.00</b>	<b>2,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >