

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

19/08/2024 16:17

JOB-NO: 50116312

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA8617T

TRANS: AUTO

CHASSIS: KMHLB41UMGU089120

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU707360

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	900.00	0.00	900.00		Y	800
2 RUST PROOFING	1.00	80.00	0.00	80.00		Y	6540
3 SUNDRIES	1.00	60.00	0.00	60.00	1810	Y	20
4 DIAGNOSTIC(CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	1.00	180.00	0.00	180.00		Y	80
5 R&R RADIATOR & CONDENSOR & TURBO INTERCOOLER	1.00	150.00	0.00	150.00		Y	120
6 VACUUM & TOP UP AIR COND GAS R-134A	1.00	150.00	0.00	150.00		Y	120
7 ADJUST HEADLAMP AIM	1.00	80.00	0.00	80.00		Y	30
8 CONDUCT 4 WHEEL ALIGNMENT & BALANCING	1.00	150.00	0.00	150.00		Y	Xm
9 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
10 RESPRAY FRONT BUMPER TOW CAP	1.00	100.00	0.00	100.00		Y	Xm
11 RESPRAY FRONT FENDER RH	1.00	250.00	0.00	250.00		Y	200
12 RESPRAY FRONT BONNET	1.00	250.00	0.00	250.00		Y	200
TOTAL:		2,600.00	0.00	2,600.00			
<u>MATERIALS</u>							
1 FRONT BUMPER <i>tom</i>	1.00	599.68	119.94	479.74	L	Y	
2 FRONT BUMPER RETAINER RH <i>cm</i>	1.00	48.32	9.66	38.66	L	Y	
3 FRONT BUMPER RADIATOR GRILLE <i>cm</i>	1.00	1,110.10	222.02	888.08	L	Y	
4 FRONT BUMPER RADIATOR GRILLE LOGO <i>cm</i>	1.00	142.84	28.57	114.27	L	Y	
5 FRONT BUMPER RADIATOR GRILLE CHROME MOULDING <i>cm</i>	1.00	121.77	24.35	97.42	L	Y	
6 FRONT BUMPER RADIATOR GRILLE UPPER COVER <i>cm</i>	1.00	138.22	27.64	110.58	L	Y	5178.42
7 FRONT BUMPER TOW CAP <i>cm</i>	1.00	28.92	5.78	23.14	L	Y	
8 FRONT BUMPER FOG LAMP COVER RH <i>cm</i>	1.00	178.55	35.71	142.84	L	Y	
9 FRONT BUMPER TOP GARNISH <i>cm</i>	1.00	125.30	25.06	100.24	L	Y	
10 FRONT FENDER RH <i>bt</i>	1.00	659.50	131.90	527.60	L	Y	
11 FRONT FENDER INNER LINER RH <i>mis</i>	1.00	185.12	37.02	148.10	L	Y	
12 FRONT SUPPORT PANEL <i>cm</i>	1.00	962.87	192.57	770.30	L	Y	
13 WIPER TANK <i>de</i>	1.00	96.42	19.28	77.14	L	Y	
14 WIPER TANK MOTOR <i>cm</i>	1.00	68.43	13.69	54.74	L	Y	
15 WIPER TANK CAP <i>cm</i>	1.00	15.22	3.04	12.18	L	Y	
16 HEADLAMP RH <i>bro</i>	1.00	1,808.10	361.62	1,446.48	L	Y	
17 FRONT BONNET <i>bt</i>	1.00	1,812.68	362.54	1,450.14	L	Y	
18 FRONT WHEEL CAP RH <i>cm</i>	1.00	265.50	53.10	212.40	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
19 FRONT BUMPER CLIP SET <i>na</i>	1.00	55.00	0.00	55.00	S	Y	30
20 FRONT BUMPER TOP GARNISH CLIP SET <i>X11</i>	1.00	35.00	0.00	35.00	S	Y	X
21 FRONT FENDER INNER LINER CLIP SET RH <i>na</i>	1.00	45.00	0.00	45.00	S	Y	30
22 RADIATOR COOLANT <i>na</i>	1.00	60.00	0.00	60.00	S	Y	40
TOTAL:		8,562.54	673.49	6,889.05			

TOTAL PARTS & LABOUR : 11,162.54 1,673.49 9,489.05

EXCESS/LOADING:\$\$ 0.00

No. Of Day: 7 days

RE-SURVEY: BEFORE AFTER PAINTING
PART-BY-PART OR LUMP SUM \$\$

DATE OF SURVEY: 20 / 08 / 24

SURVEYED BY: Rasul

CONTACT NO: 90010018 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
60190078

Ding Auto User 1

ESTIMATOR
STAAUTOCENTRE

TEL: _____ FAX: _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: