



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP111
Raphne

LIM BOON CHIP
BLK 117A RIVERVALE DRIVE #05-76
SINGAPORE 541117

TAX INVOICE

Repair Code : CLM18348

Date in : 19/08/2024

Vehicle Num. : SFG9099Z

Model : KIA CERATO 1.6(A) EX

Chassis/Eng# : KNAF3416MK5031211/G4FGJH722194

Contact : 93392642 98221629

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dented</i>	1	1298.00	1,298.00 ✓
REAR BOOTLID 'C&C' EMBLEM	1	88.00	88.00 ✓
REAR BOOTLID 'CERATO' EMBLEM	1	28.00	28.00 ✓
REAR BOOTLID 'LOGO' EMBLEM	1	32.00	32.00 ✓
REAR BOOTLID CAMERA WITH LOCK SWITCH <i>new</i>	1	718.00	718.00 +
REAR BOOTLID CENTER REFLECTOR <i>new</i>	1	623.00	623.00 +
REAR BOOTLID HINGES L/R <i>new</i>	2	88.00	176.00 +
REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>	2	8.00	16.00 +
REAR BOOTLID INNER TRIM BOARD <i>new</i>	1	182.00	182.00 +
REAR BOOTLID LOCK STRIKER <i>new</i>	1	38.00	38.00 +
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	101.00	101.00 ✓
REAR BOOTLID REFLECTOR L/R <i>LH cancelled</i>	2	549.00	1,098.00 549 ✓
REAR BOOTLID WEATHER STRIP <i>new</i>	1	90.00	90.00 +
REAR BUMPER <i>Dented</i>	1	652.00	652.00 ✓
REAR BUMPER INNER ANTENNA SENSOR <i>cancelled</i>	1	148.00	148.00 ✓
REAR BUMPER LOWER LID <i>Dented</i>	1	348.00	348.00 ✓
REAR BUMPER REINFORCEMENT <i>cancelled</i>	1	287.00	287.00 ✓
REAR BUMPER REINFORCEMENT BRACKET L/R <i>L-R Dented</i>	2	70.00	140.00 70 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM BOON CHIP
BLK 117A RIVERVALE DRIVE #05-76
SINGAPORE 541117

TAX INVOICE

Repair Code : CLM18348

Date in : 19/08/2024

Vehicle Num. : SFG9099Z

Model : KIA CERATO 1.6(A) EX

Chassis/Eng# : KNAF3416MK5031211/G4FGJH722194

Contact : 93392642 98221629

REAR BUMPER REINFORCEMENT LOWER BRACKET	<i>Repd</i>	3	11.00	33.00	✓
REAR BUMPER REINFORCEMENT TOP BRACKET L/R	<i>Repd</i>	2	11.00	22.00	✓
REAR BUMPER SIDE RETAINER L/R	<i>LH curled</i>	2	23.00	46.00	23
REAR BUMPER SIGNAL LAMP GARNISH L/R	<i>LH ut</i>	2	90.00	180.00	90
REAR BUMPER SIGNAL LAMP L/R	<i>LH curled</i>	2	163.00	326.00	163
REAR BUMPER UNDER COVER LH	<i>torn</i>	1	60.00	60.00	✓
REAR END PANEL	<i>Dented</i>	1	305.00	305.00	✓
REAR END PANEL INNER TOP GARNISH	<i>Dented</i>	1	38.00	38.00	✓
REAR FENDER INNER TRIM BOARD L/R	<i>LH torn</i>	2	396.00	792.00	396
REAR FLOOR PANEL	<i>New</i>	1	649.00	649.00	✓
REAR FLOOR PANEL TOP BOARD COVER L/R	<i>torn</i>	2	269.00	538.00	269
REAR TAILLAMP INNER PANEL L/R	<i>New</i>	2	122.00	244.00	✓
REAR TAILLAMP L/R	<i>LH curled</i>	2	609.00	1218.00	609
Subtotal before discount				10,514.00	
Percentage discount 10%				1,051.40	
Sub-total 1				9,462.60	
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	<i>New</i>	1	50.00	50.00	✓
REAR BOOTLID NUMBER PLATE	<i>New</i>	1	25.00	25.00	✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LIM BOON CHIP
BLK 117A RIVERVALE DRIVE #05-76
SINGAPORE 541117

Contact : 93392642 98221629

TAX INVOICE

Repair Code : CLM18348

Date in : 19/08/2024

Vehicle Num. : SFG9099Z

Model : KIA CERATO 1.6(A) EX

Chassis/Eng# : KNAF3416MK5031211/G4FGJH722194

REAR BOOTLID NUMBER PLATE HOLDER <i>new</i>	1	50.00	50.00 <i>+</i>
REAR BUMPER CLIPS - SET <i>new</i>	1	60.00	60.00 30
REAR BUMPER REVERSE SENSOR <i>new</i>	1	280.00	280.00 20
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	40.00	40.00 10
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>new</i>	2	50.00	100.00 30
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	25.00	50.00 <i>+</i>
Subtotal before discount			655.00
Percentage discount 0%			0.00
Sub-total 2			655.00
Parts-total			10,117.60

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear bootlid mechanism lock outer handle reflector

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance

*** This is a computer-generated document which requires no signature.***

Labour Total

2,680.00

Parts & Labour Total

12,797.60

Acknowledged by Repairer
Signature:
Date:

page 3

Adrian
1/s 20/08/24

062p

total: 6978.10
1/s: 5.5K