

ASSIGNMENT

From: _____ Date: _____

Estn: Estn

OD / TP RES / CD RES / EVA / INV / MV

To In: Vehicle No:

at W/O in/s

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNH 3091J Yr Regn: 2018 / Sept.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Bmw 530i C.D. 1998

Colour: Beige A/C: Insured / Std / NI / NA

Sp. Reading: 83823 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAJAS2050WC07976

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R18

R: 245/45 R18

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 20/08/24

Survey held at JL Perfect

Des. of Damages: Fr Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP III</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV</u>
	<u>PV</u>
	<u>Nett</u>
	<u>430L</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS \$

Photos _____

Others _____

Report Format: _____

Report Form: _____

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 16.08.2024

TO : INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
VEHICLE NO : SNH3091J
MODEL : BMW 520i
DATE OF ACCIDENT : 16.08.2024
TIME OF ACCIDENT : 13:00 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>born</i>	1	\$ 1,979.85	\$ 1,979.85
2	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 85.92	\$ 85.92
3	FRONT BUMPER FOGLAMP <i>new</i>	2	\$ 550.85	\$ 1,101.70
4	FRONT BUMPER FOGLAMP TOP GARNISH <i>new</i>	2	\$ 198.30	\$ 396.60
5	FRONT BUMPER FOGLAMP COVER <i>new</i>	2	\$ 114.80	\$ 229.60
6	FRONT BUMPER FOGLAMP INNER GARNISH <i>new</i>	2	\$ 154.10	\$ 308.20
7	FRONT BUMPER SENSOR <i>new</i>	4	\$ 265.55	\$ 1,062.20
8	FRONT BUMPER SENSOR HOLDER <i>new</i>	6	\$ 119.87	\$ 719.22
9	FRONT BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 324.85	\$ 324.85
10	FRONT BUMPER TOP GARNISH RUBBER <i>new</i>	1	\$ 60.50	\$ 60.50
11	FRONT BUMPER BRACE PANEL <i>best</i>	1	\$ 198.30	\$ 198.30
12	FRONT BUMPER LOWER BEAM <i>new</i>	1	\$ 498.30	\$ 498.30
13	FRONT BUMPER LOWER BEAM GARNISH <i>new</i>	1	\$ 100.10	\$ 100.10
14	FRONT BUMPER SIDE BRACKET <i>new</i>	2	\$ 30.10	\$ 60.20
15	FRONT BUMPER TOP SUPPORT BEAM <i>new</i>	1	\$ 289.75	\$ 289.75
16	FRONT BUMPER REINFORCEMENT <i>perked</i>	1	\$ 797.25	\$ 797.25
17	FRONT BUMPER REINFORCEMENT SPONGE <i>curled</i>	1	\$ 115.90	\$ 115.90
18	BONNET <i>perked</i>	1	\$ 2,734.90	\$ 2,734.90
19	BONNET LOGO <i>new</i>	1	\$ 115.10	\$ 115.10
20	BONNET HINGE <i>2 H</i>	2	\$ 150.58	\$ 301.16
21	BONNET HINGE DAMPER <i>1 H</i>	2	\$ 180.12	\$ 360.24

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNH3091J**
 MODEL : **BMW 520i**
 DATE OF ACCIDENT : **16.08.2024**
 TIME OF ACCIDENT : **13:00 HOURS**

22	BONNET LOCK <i>new</i>	2	\$ 250.20	\$ 500.40	+
23	BONNET LOCK HOLDER PANEL SUPPORT <i>new</i>	2	\$ 271.75	\$ 543.50	+
24	BONNET LOCK CATCHER <i>new</i>	2	\$ 104.54	\$ 209.08	+
25	BONNET LOCK CABLE	1	\$ 66.54	\$ 66.54	+
26	BONNET INSULATOR <i>new</i>	1	\$ 280.54	\$ 280.54	+
27	BONNET STOPPER (SMALL)	3	\$ 10.05	\$ 30.15	+
28	BONNET STOPPER (BIG)	2	\$ 20.10	\$ 40.20	+
29	FRONT CAMERA <i>new</i>	1	\$ 900.60	\$ 900.60	+
30	FRONT CAMERA COVER GARNISH <i>new</i>	1	\$ 48.65	\$ 48.65	+
31	FRONT GRILLE C/W CHROME <i>new</i>	2	\$ 191.85	\$ 383.70	+
32	FRONT AIR GUARD C/W WIND (UPPER) <i>new</i>	1	\$ 365.40	\$ 365.40	+
33	FRONT AIR GUARD C/W WIND MOTOR <i>new</i>	1	\$ 251.30	\$ 251.30	+
34	FRONT AIR GUARD TOP <i>new</i>	1	\$ 150.10	\$ 150.10	+
35	FRONT AIR GUARD (LOWER) <i>new</i>	1	\$ 150.10	\$ 150.10	+
36	FRONT CHASSIS CROSS BAR <i>new</i>	1	\$ 97.65	\$ 97.65	+
37	FRONT LOWER GRILLE (CENTER) <i>new</i>	1	\$ 139.40	\$ 139.40	+
38	FRONT LOWER GRILLE (SIDE) <i>new</i>	2	\$ 118.60	\$ 237.20	+
39	FRONT SUPPORT PANEL <i>new</i>	1	\$ 266.50	\$ 266.50	+
40	FRONT SUPPORT PANEL TOP COVER <i>new</i>	2	\$ 114.69	\$ 229.38	+
41	FRONT PANEL CROSS BRACKET <i>new</i>	2	\$ 82.65	\$ 165.30	+
42	AIRCON CONDENSER <i>new</i>	1	\$ 1,263.15	\$ 1,263.15	+
43	HORN	2	\$ 120.81	\$ 241.62	+
44	OUTSIDE TEMPERATURE SENSOR <i>new</i>	1	\$ 120.00	\$ 120.00	+
45	HEADLAMP (LED) <i>new</i>	2	\$ 5,119.95	\$ 10,239.90	5119.95
46	HEADLAMP TOP COVER GARNISH <i>new</i>	2	\$ 100.50	\$ 201.00	+
47	HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 186.20	\$ 372.40	+
48	FRONT FENDER COWLING <i>new</i>	2	\$ 168.50	\$ 337.00	+
49	FRONT FENDER TOP COVER GARNISH <i>new</i>	2	\$ 115.60	\$ 231.20	+
50	ENGINE UNDERCOVER <i>new</i>	1	\$ 708.80	\$ 708.80	+

TOTAL PRICE \$ 30,610.60
 LESS 5% \$ 1,530.53
SUB TOTAL PRICE \$ 29,080.07

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNH3091J**
 MODEL : **BMW 520i**
 DATE OF ACCIDENT : **16.08.2024**
 TIME OF ACCIDENT : **13:00 HOURS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>curbed</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	FRONT BUMPER TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	FRONT BUMPER BOTTOM SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	ENGINE UNDERCOVER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	FRONT FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	BONNET SEALANT <i>34</i>	1	\$ 120.00	\$ 120.00
8	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
9	FRONT AIR GUARD SIDE GARNISH CLIP (SET) <i>34</i>	1	\$ 30.00	\$ 30.00
10	FRONT AIR GUARD TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
11	COOLANT <i>new</i>	1	\$ 150.00	\$ 150.00

TOTAL \$ 690.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	<i>500</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>400</i>
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>x</i>
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>x</i>
5	REMOVE AND REFIX INTER COOLER	\$ 80.00	<i>x</i>
6	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
7	REMOVE AND REFIX FRONT CAMERA	\$ 120.00	<i>50</i>

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNH3091J**
MODEL : **BMW 520i**
DATE OF ACCIDENT : **16.08.2024**
TIME OF ACCIDENT : **13:00 HOURS**

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 580.00	X
---	--	-----------	---

TOTAL \$ **4,040.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 29,770.07
TOTAL LABOUR COST : \$ 4,040.00
TOTAL REPAIR COST : \$ 33,810.07

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP :8297 9787

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
1/s 20/08/24
04 Days.