

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709586

Date : 20/08/2024

Vehicle Num. : SLS1521P

Make/Model : MERCEDES S350

Chassis/Eng# :

Accident Date : 14/08/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	O/S FRONT DOOR	3756.94	3,785.00 ✓
2.	1PC	O/S FRONT DOOR LOCK	605.10	745.00 ✓
3.	1PC	O/S FRONT DOOR WEATHERSTRIP	335.72	418.00 ✓
4.	1PC	O/S FRONT DOOR REGULATOR GEAR		955.00 X
5.	1PC	O/S FRONT DOOR REGULATOR MOTOR		694.00 X
6.	1PC	O/S FRONT DOOR OUTER HANDLE	423.52	502.00 ✓
7.	1PC	O/S FRONT DOOR LOWER CHROME	118.00	284.00 ✓
8.	1PC	O/S WING MIRROR		2,579.00 X
9.	1PC	O/S WING MIRROR LAMP		319.00 X
10.	1PC	O/S REAR DOOR	4005.92	4,466.00 ✓
11.	1PC	O/S REAR DOOR HINGE - TOP		271.00 X
12.	1PC	O/S REAR DOOR HINGE - BOTTOM		275.00 X
13.	1PC	O/S REAR DOOR LOCK		745.00 X
14.	1PC	O/S REAR DOOR WEATHERSTRIP	332.00	418.00 ✓
15.	1PC	O/S REAR DOOR CHECKER		315.00 X
16.	1PC	O/S REAR DOOR REGULATOR GEAR		955.00 X
17.	1PC	O/S REAR DOOR REGULATOR MOTOR		694.00 X
18.	1PC	O/S REAR DOOR LOWER CHROME	201.00	274.00 ✓
19.	1PC	O/S SIDE SKIRT		1,394.00 X
20.	1PC	O/S REAR DOOR OUTER HANDLE		502.00 X
21.	1PC	REAR WINDSCREEN WITH MOULDING		3,330.00 X
22.	1PC	O/S REAR FENDER		6,902.00 X

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709586

Date : 20/08/2024

Vehicle Num. : SLS1521P

Make/Model : MERCEDES S350

Chassis/Eng# :

Accident Date : 14/08/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1PC	O/S REAR FENDER INNER SHIELD <i>11 X</i>		383.00 X
24.	1PC	REAR BUMPER <i>217/70.1</i>	2102.32	2,455.00 X
25.	1PC	O/S REAR BUMPER SIDE RETAINER <i>11 X</i>		90.00 X
26.	1PC	O/S REAR BUMPER CHROME <i>11 X</i>	112.00	241.00 X
27.	1PC	O/S REAR RIM <i>11 X</i>	1600.00	2,484.00 X
28.	1PC	O/S REAR SHOCK ABSORBER <i>11 X</i>		4,950.00 X
29.	1PC	O/S REAR WHEEL HUB <i>11 X</i>		506.00 X
30.	1PC	O/S REAR WHEEL BEARING <i>11 X</i>		566.00 X
List TotalS\$:				42,497.00
10.00% Discount S\$:				4,249.70
				38,247.30
SPECIAL NETT ITEMS :				
1.	1SET	O/S FRONT DOOR RIVETS <i>11 X</i>		80.00 X
2.	1SET	O/S FRONT DOOR INNER TRIM CLIPS <i>11 X</i>		40.00 X
3.	1SET	O/S SIDE SKIRT CLIPS <i>11 X</i>		40.00 X
4.	1PC	REAR WINDSCREEN INNER SEAL <i>11 X</i>		80.00 X
5.	1PC	REAR WINDSCREEN SEALANT <i>11 X</i>		40.00 X
6.	1SET	O/S REAR FENDER INNER SHIELD CLIPS <i>11 X</i>		40.00 X
7.	1SET	REAR BUMPER CLIP <i>11 X</i>		40.00 X
8.	1SET	REAR BUMPER RIVET <i>11 X</i>		80.00 X
Special Nett Total S\$:				440.00

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709586

Date : 20/08/2024

Vehicle Num. : SLS1521P

Make/Model : MERCEDES S350

Chassis/Eng# :

Accident Date : 14/08/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO CHECK REAR PORTION WIRING
TO FIT REVERSE SENSOR IN BUMPER
TO RESET CLEARANCE SONAR USING DIAGNOSTIC SCANNER
TO TRANSFER REAR WINDSCREEN GLASS
TO REMOVE FUEL TANK TO ENABLE REPAIR & FIX BACK
TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS
TO TRANSFER DOOR GLASS
TO TRANSFER DOOR MECHANISM
TO TRANSFER AND BALANCE TYRES
TO REPLACE DAMAGED UNDERCARRIAGE PARTS.
TO CONDUCT COMPETETERIZE FOUR WHEEL ALIGNMENT
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD
O/S REAR FENDER, REPLACEMENT OF PARTS AND ALIGN THE SAME
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA

	50.00	20
	50.00	30
11	350.00	X
11	150.00	X
11	350.00	X
	250.00	60
11	300.00	X
	300.00	100
11	50.00	X
11	350.00	X
11	120.00	X
	1,600.00	600
	2,000.00	900
	5,920.00	

Labour Total S\$:

E. & O.E.

Total S\$: 44,607.30

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-13598-82
102
1223867
40
1710
13598-07