

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 19.08.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBM4657L**
MODEL : **HONDA N VAN**
DATE OF ACCIDENT : 18.08.2024
TIME OF ACCIDENT : 12:10 HOURS

Xiao Chun.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,456.20	\$ 1,456.20
2	TAILGATE LOGO <i>new</i>	1	\$ 30.20	\$ 30.20
3	TAILGATE STICKER 'CHINESE WORD' <i>new</i>	1	\$ 58.60	\$ 58.60
4	TAILGATE WINDSCREEN GLASS <i>Shattered</i>	1	\$ 1,442.20	\$ 1,442.20
5	SIDE CENTRE RAILWAY JOINT (RH) <i>new</i>	1	\$ 685.30	\$ 685.30
6	TAILLAMP RH <i>new</i>	1	\$ 479.20	\$ 479.20
7	REAR BUMPER (SIDE) RH <i>2x2</i>	1	\$ 371.20	\$ 371.20
8	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 73.20	\$ 146.40
9	REAR BUMPER REVERSE HOLDER <i>new</i>	2	\$ 80.50	\$ 161.00

2987.20

2389.76

TOTAL PRICE \$ 4,830.30
LESS 20% \$ 966.06
SUB TOTAL PRICE \$ 3,864.24

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
3	TAILGATE INNER LOCK COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
4	TAIL GATE INNER BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
5	TAIL GATE '70KM/H' STICKER <i>new</i>	1	\$ 40.00	\$ 40.00
6	TAIL GATE STICKER (SPECAIL TYPE)(BLACK) <i>new</i>	1	\$ 350.00	\$ 350.00
7	TAIL GATE WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBM4657L**
 MODEL : **HONDA N VAN**
 DATE OF ACCIDENT : 18.08.2024
 TIME OF ACCIDENT : 12:10 HOURS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

8	TAIL GATE WINDSCREEN SEALANT <i>ew</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
9	TAIL GATE WINDSCREEN SOLAR FILM <i>ew</i>	1	\$ 250.00	\$ 250.00	<i>20</i>
10	REAR SIDE PANEL STICKER (RH) <i>ew</i>	1	\$ 450.00	\$ 450.00	<i>+</i>

545 TOTAL \$ 1,550.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	<i>20</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>20</i>
3	TUFF COAT	\$ 250.00	<i>x</i>
4	WIRING CHECK	\$ 180.00	<i>x</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 150.00	<i>x</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>x</i>
7	TRANSFER TAILGATE MECHANISM	\$ 120.00	<i>60</i>
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>x</i>
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

580

LKK Auto Consultants hence notify the Repairer of the following:

ESTIMATE REPORT

TOTAL PARTS COST \$ 5,414.24

TOTAL LABOUR COST \$ 3,360.00

TOTAL REPAIR COST \$ 8,774.24

• No illegal modification(s) is allowed

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

Acknowledged by Repairer

Signature: _____

Date: _____

\$3,360.00

Adnan L
2/8 20/08/24
03 hrs.

blub: 351476
1/5: 2.81C ✓