

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE : 19.08.2024

TO	:	INCOME	MOTOR CLAIMS DEPTS
VEHICLE NO	:	GBG3852C	
MODEL	:	NISSAN NV350	
DATE OF ACCIDENT	:	18.08.2024	
TIME OF ACCIDENT	:	14:45 HOURS	

Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Det'd</i>	1	\$ 688.70	\$ 688.70
2	REAR BUMPER STEP PANEL <i>Det'd</i>	1	\$ 269.60	\$ 269.60
3	REAR BUMPER SIDE HOLDER CLIP <i>n</i>	6	\$ 7.50	\$ 45.00
4	TAIL LAMP <i>LH ut.</i>	2	\$ 298.70	\$ 597.40
5	TAIL GATE <i>Det'd</i>	1	\$ 2,101.40	\$ 2,101.40
6	TAIL GATE EMBLEM 'NV350' <i>3 per</i>	1	\$ 89.70	\$ 89.70
7	TAIL GATE LOGO	1	\$ 80.30	\$ 80.30
8	TAIL GATE SIDE STOPPER <i>den</i>	2	\$ 19.00	\$ 38.00
9	TAILGATE DAMPER <i>den</i>	2	\$ 175.40	\$ 350.80
10	TAIL GATE OUTER MOULDING <i>den</i>	1	\$ 463.90	\$ 463.90
11	TAIL GATE WEATHER STRIP <i>ut</i>	1	\$ 269.30	\$ 269.30
12	TAIL GATE WEATHER STRIP PROTECTOR <i>Det'd</i>	1	\$ 258.20	\$ 258.20
13	TAIL GATE INNER LOCK <i>Det'd</i>	1	\$ 394.10	\$ 394.10
14	TAIL GATE INNER LOCK MOTOR <i>den</i>	1	\$ 267.30	\$ 267.30
15	TAIL GATE LOCK COVER GARNISH <i>anhd</i>	1	\$ 68.30	\$ 68.30
16	TAIL GATE CATCH <i>den</i>	1	\$ 31.80	\$ 31.80
17	REAR END PANEL (OUTER) <i>Det'd</i>	1	\$ 461.60	\$ 461.60
18	REAR END PANEL (INNER) <i>Det'd</i>	1	\$ 986.70	\$ 986.70
19	REAR FLOOR PANEL <i>den</i>	1	\$ 1,883.20	\$ 1,883.20
20	REAR FLOOR MAT <i>den</i>	1	\$ 867.00	\$ 867.00
21	SPARE TYRE CHAIN <i>MTW</i>	1	\$ 294.70	\$ 294.70

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBG3852C**
 MODEL : **NISSAN NV350**
 DATE OF ACCIDENT : 18.08.2024
 TIME OF ACCIDENT : 14:45 HOURS

22	SPARE TYRE CHAIN SUPPORT MEMBER	1	\$ 387.60	\$ 387.60
----	---------------------------------	---	-----------	-----------

5596.60
5396.94

TOTAL PRICE \$ 10,894.60
 LESS 10% \$ 1,089.46
SUB TOTAL PRICE \$ 9,805.14

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
3	TAIL GATE INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
4	TAIL GATE OUTER MOULDING CLIP (SET)	1	\$ 30.00	\$ 30.00
5	TAIL GATE STICKER "70KM/H"	1	\$ 40.00	\$ 40.00
6	TAIL GATE STICKER "4PAX"	1	\$ 40.00	\$ 40.00
6	TAIL GATE COMPANY STICKER (SPECAIL TYPE)	1	\$ 500.00	\$ 500.00
7	TAIL GATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
8	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
9	TAIL LAMP CLIP (SET)	1	\$ 30.00	\$ 30.00
11	REAR END PANEL (OUTER) SEALANT	1	\$ 150.00	\$ 150.00
12	REAR FLOOR PANEL TOP BOARD(WOODER)	1	\$ 1,500.00	\$ 1,500.00
13	REVERSE SENSOR	1	\$ 220.00	\$ 220.00

1090 TOTAL \$ 2,750.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,000.00	700
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	700
3	TUFF COAT	\$ 250.00	60
4	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBG3852C**
MODEL : **NISSAN NV350**
DATE OF ACCIDENT : 18.08.2024
TIME OF ACCIDENT : 14:45 HOURS

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x
---	--	-----------	---

1690

TOTAL \$ 4,590.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,555.14
TOTAL LABOUR COST : \$ 4,590.00
TOTAL REPAIR COST : \$ 17,145.14

Admin L
2/s 20/08/24
06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 8176.54
L/S: 6550

6550

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: