

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2400089

INV Date : 17-07-2024

Reference CS/SMR24060113/Unp3

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SLD 9343M
Insured Veh. SHB 5669H
Claim No. TAX/06/24/2041
Policy No.
Accident Date 14/06/2024
Inspection Date 18/06/2024

Description	Amount
Survey Inspection	128.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS STRIDES PREMIER AUTOMOTIVE SERVICES PL.	Ref:	CS/SMR24060113/Unp3
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Date:	18/06/2024
	Code:	SMR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 5669H	Veh. Inspected	SLD 9343M
Policy No.	-	Coverage	0
Claim No.	TAX/06/24/2041	Excess	\$0.00
Assign From	HUA YEN	Assign Date	18/06/2024

2. Vehicle Details

Make & Model	HONDA VEZEL HYBRID (A)	C.C	1496
Engine No.	LEB5064312	Year of Reg.	30/06/2016
Chassis No.	RU31114300	Colour	WHITE
Odometer	278148 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R17	BRIDGESTONE	5
L/H Front Tyre	225/55R17	BRIDGESTONE	5
R/H Rear Tyre	225/55R17	BRIDGESTONE	5
L/H Rear Tyre	225/55R17	BRIDGESTONE	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/06/2024	Inspection Date	18/06/2024
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLD 9343M

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN MOULDING	NECESSARY	\$110.20	\$110.20
1	TAILGATE	DENTED/BENT	\$1,099.20	\$1,099.20
1	TAILGATE "VEZEL" EMBLEM	NECESSARY	\$66.80	\$66.80
1	TAILGATE "H" LOGO	NOT NECESSARY	\$45.00	\$0.00
1	TAILGATE OUTER HANDLE GARNISH	NOT NECESSARY	\$450.00	\$0.00
2	TAILGATE REFLECTORS @\$386.20	NOT NECESSARY	\$772.40	\$0.00
1	TAILGATE INNER LOCK	BENT	\$199.80	\$199.80
1	TAILGATE LOCK STRIKER	NOT NECESSARY	\$66.00	\$0.00
1	TAILGATE INNER TRIM BOARD	DEFORMED/CRACKED	\$435.00	\$435.00
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	\$50.00	\$50.00
1	TAILGATE WEATHERSTRIP	TWISTED	\$288.00	\$288.00
1	REAR BUMPER	DENTED	\$980.00	\$762.00
2	REAR BUMPER SIDES @\$235.10	BUCKLED	\$470.20	\$470.20
2	REAR BUMPER REFLECTORS @\$151.00	CRACKED	\$302.00	\$302.00
1	REAR BUMPER UNDER COVER	DEFORMED/TWISTED	\$541.00	\$388.20
1	SET REAR BUMPER UNDER COVER CLIPS	NECESSARY	\$50.00	\$50.00
1	SET REAR BUMPER CLIPS	NECESSARY	\$50.00	\$50.00
1	REAR END PANEL	BADLY DENTED	\$665.20	\$517.00
1	REAR END PANEL TOP GARNISH	TWISTED	\$341.10	\$266.00
2	TAILLAMPS @\$650.00	CRACKED	\$1,300.00	\$1,081.60
2	TAILLAMP HOUSING PANELS @\$350.00	TO REPAIR SEE LABOUR	\$700.00	\$0.00
1	REAR BUZZLE SENSOR	CRACKED	\$98.00	\$98.00
2	REAR FENDERS @\$1090.00	TO REPAIR SEE LABOUR	\$2,180.00	\$0.00
2	REAR FENDER OUTER PROTECTORS @\$380.00	DEFORMED/TORN	\$760.00	\$590.00
2	REAR FENDER INNER TRIM BOARDS @\$395.00	DEFORMED/TORN	\$790.00	\$790.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	\$1,280.00	\$0.00
1	REAR FLOOR PANEL TOP BOARD	TORN	\$522.00	\$392.30
1	REAR FLOOR PANEL TOP TRAY	CRACKED	\$585.00	\$366.50
1	REAR EXHAUST	NOT NECESSARY	\$765.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	\$108.00	\$0.00
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$1,674.56)
			\$16,069.90	\$6,698.24

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$50.00	\$40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	\$50.00	\$20.00
1	REAR BUMPER LOWER SKIRTING SILVER (SN)	TORN	\$200.00	\$200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	\$50.00	\$30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	MALFUNCTION	\$280.00	\$20.00
1	SET REAR REVERSE CAMERA (SN)	NOT NECESSARY	\$450.00	\$0.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	\$120.00	\$0.00
1	TAILGATE "HYBRID" EMBLEM (SN)	NECESSARY	\$45.00	\$45.00
			\$1,245.00	\$355.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING		\$50.00	\$20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR		\$80.00	\$30.00
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	\$120.00
	TO TRANSFER TAILGATE MECHANISM		\$100.00	\$50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	\$60.00
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM		\$180.00	\$0.00
	TO DISMANTLE & REFIX REAR EXHAUST		\$100.00	\$0.00
	TO SPRAY RUST PROOFING		\$100.00	\$50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS, REAR FENDERS AND REAR FLOOR PANEL		\$1,800.00	\$800.00
	TO PUTTY & SPRAY PAINTING		\$1,500.00	\$1,000.00
			\$4,180.00	\$2,130.00

GRAND TOTAL			\$21,494.90	\$9,183.24
--------------------	--	--	--------------------	-------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$7,300.00
Report Ref No: CS/SMR24060113/Unp3			

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	14/06/2024 13:59 (SGT)
Reported by	Actual Driver
Date of Accident	14/06/2024 09:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Junction of Admiralty Road towards Marsiling Drive
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD9343M
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	HENG HENG LIMO SERVICE
Company Reg No	53346568X
Email Address	winston.heng@yahoo.com.sg
Mobile Phone No	(Phone) +65-96324224
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	VEZEL 1.5X HYBRID CVT ABS D/AIRBAG 2WD
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5116643769-03

DRIVER

Name of Driver	Heng Siew Hwang
NRIC No	S1592837I
Date Of Birth	19/05/1963
Occupation	Outdoor

Driving Pass Date	16/11/1981
Driving experience	42 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96324224
Alt. Phone Number	-
Email Address	winston.heng@yahoo.com.sg
Address	104 Aljunied Crescent #11-247 S380104
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	owner
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer to attached

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	file with owner

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB5669H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	Ng Kim San

NRIC No	S6910722B
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Heng Siew Hwang
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLD9343M
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

14/6/2024
1330hrs.

HENG HENG
LIMO SERVICE


[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A = SLD 9343M

B = SHB 5669H

Describe Circumstances of the Accident

On 14.06.2024 at about 0918hrs. I was stationary due to the front traffic along junction of Admiralty Rd toward Marsiling Dr. Suddenly, I felt an impact. The vehicle SHB 5669H collided onto rear portion of my vehicle SLD 9343M.

Declaration

We declare the foregoing particulars are true in every respect.

14/6/2024
1330 hrs. HENG HENG
LIMO SERVICE



14 Jun 2024 12.55pm

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M




PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M




PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 12 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M




PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M




PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M




PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 20 of 20)

PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M



PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLD 9343M

