

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ONG MENG HOCK
BLK 76 BEDOK NORTH RD #13-178
SINGAPORE 460076

Contact : 98220028

TP INC
VERON
TAX INVOICE

Repair Code : CLM16399

Date in : 17/08/2024

Vehicle Num. : SMQ9229E

Model : AUDI A4 1.4 TFSI S TRONIC

Chassis/Eng# : WAUZZZF4XGA012721/CVN001843

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>Warped</i>	1	1800.17	✓ 1,800.17
ENGINE UNDER COVER <i>new</i>	1	799.69	+ 799.69
FRONT BONNET <i>new</i>	1	2300.97	+ 2,300.97
FRONT BONNET HINGES L/R	2	299.70	+ 599.40
FRONT BONNET INNER RUBBER SEAL	1	188.96	+ 188.96
FRONT BONNET INNER STOPPER L/R	4	80.99	+ 323.96
FRONT BONNET MECHANISM LOCK	1	400.33	+ 400.33
FRONT BUMPER <i>delivered</i>	1	2333.90	✓ 2,333.90
FRONT BUMPER FOGLAMP GARNISH L/R <i>also 2H could</i>	2	233.91	233.91 / 467.82
X FRONT BUMPER FOGLAMP L/R <i>new</i>	2	289.79	+ 579.58
FRONT BUMPER REINFORCEMENT <i>delivered</i>	1	899.77	✓ 899.77
FRONT BUMPER REINFORCEMENT BRACKET L/R <i>new</i>	2	400.33	+ 800.66
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	80.97	+ 161.94
X FRONT BUMPER SPONGE <i>new</i>	1	200.77	+ 200.77
FRONT BUMPER UDNER COVER <i>new</i>	1	800.77	+ 800.77
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	98.00	- 98.00
FRONT GRILLE ASSY <i>could</i>	1	1600.85	- 1,600.85
FRONT GRILLE TOP GARNISH <i>could</i>	1	288.79	✓ 288.79

*** This is a computer-generated document which requires no signature.***

page 1

Front bumper lower grille

\$ 205.00 ✓

Front bumper inner top bracket

\$ 335.00 ✓

could

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ONG MENG HOCK
BLK 76 BEDOK NORTH RD #13-178
SINGAPORE 460076

Contact : 98220028

TAX INVOICE

Repair Code : CLM16399
Date in : 17/08/2024
Vehicle Num. : SMQ9229E
Model : AUDI A4 1.4 TFSI S TRONIC
Chassis/Eng# : WAUZZZF4XGA012721/CVN001843

FRONT HEADLAMP L/R	2	2499.60	✓	4,999.20
FRONT HEADLAMP LOWER BRACKET L/R	2	288.71	+	577.42
FRONT INTERCOOLER	1	800.91	+	800.91
FRONT SUPPORT PANEL	1	1600.77	✓	1,600.77
RADIATOR	1	1600.11	✓	1,600.11
RADIATOR FAN COWLING ASSY	1	1990.91	+	1,990.91
RADIATOR SIDE GUIDE L/R	2	133.67	+	267.34
REAR BOOTLID	1	2800.77	+	2,800.77
REAR BOOTLID 'A4' EMBLEM	1	160.75	✓	160.75
REAR BOOTLID 'LOGO' EMBLEM	1	188.11	✓	188.11
REAR BOOTLID 'TFSI' EMBLEM	1	121.17	✓	121.17
REAR BOOTLID HINGES L/R	2	233.77	+	467.54
REAR BOOTLID INNER RUBBER STOPPER	1	31.77	+	31.77
REAR BOOTLID INNER TRIM BOARD	1	488.96	+	488.96
REAR BOOTLID MECHANISM LOCK	1	400.37	+	400.37
REAR BOOTLID MECHANISM LOCK COVER	1	99.79	+	99.79
REAR BOOTLID REFLECTOR L/R	2	777.69	✓	1,555.38
REAR BOOTLID WEATHER STRIP	1	600.11	+	600.11

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ONG MENG HOCK
BLK 76 BEDOK NORTH RD #13-178
SINGAPORE 460076

Contact : 98220028

TAX INVOICE

Repair Code : CLM16399
Date in : 17/08/2024
Vehicle Num. : SMQ9229E
Model : AUDI A4 1.4 TFSI S TRONIC
Chassis/Eng# : WAUZZZF4XGA012721/CVN001843

REAR BUMPER	1	2333.70	✓	2,333.70
REAR BUMPER INNER CENTER BRACKET	1	388.75	✓	388.75
REAR BUMPER LOWER LID	1	699.33	✓	699.33
REAR BUMPER REINFROCEMENT	1	800.77	✓	800.77
X REAR BUMPER REINFROCEMENT BRACKET L/R	2	333.96	+	667.92
REAR BUMPER REVERSE SENSOR	4	233.69	467.38	934.76
REAR BUMPER REVERSE SENSOR 'O' RING	4	30.17	60	120.68
REAR BUMPER REVERSE SENSOR HOLDER	4	28.00	✓	112.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	499.70	+	499.70
REAR BUMPER SIDE RETAINER L/R	2	90.77	+	181.54
X REAR BUMPER SPONGE	1	269.10	+	269.10
REAR BUMPER TOW HOOK COVER	1	130.77	+	130.77
REAR BUMPER UNDER COVER LH RH	1	388.95	+	388.95
REAR END PANEL	1	1800.99	✓	1,800.99
REAR END PANEL ANTENNA SENSOR	1	300.17	✓	300.17
REAR END PANEL INNER TOP GARNISH	1	300.71	✓	300.71
REAR FENDER INNER TRIM BOARD L/R	2	800.91	+	1,601.82
REAR TAILLAMP L/R	2	999.77	✓	1,999.54

*** This is a computer-generated document which requires no signature.***

page 3

Rear bumper Keyless sensor cable 355.00 ✓
Rear bumper Keyless sensor module 496.00 +

ONG MENG HOCK
BLK 76 BEDOK NORTH RD #13-178
SINGAPORE 460076

Contact : 98220028

TAX INVOICE

Repair Code : CLM16399

Date in : 17/08/2024

Vehicle Num. : SMQ9229E

Model : AUDI A4 1.4 TFSI S TRONIC

Chassis/Eng# : WAUZZZF4XGA012721/CVN001843

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

80 450.00

30 80.00

150 400.00

✓ 80.00

x 100.00

600 x 1,200.00

2440 400 1,400.00

7 120 1,600.00

x 150.00

Labour Total

4,860.00

Parts & Labour Total

47,935.41

*** This is a computer-generated document which requires no signature.***

page 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adm
1/2 20/08/24

X60 of days ???

10 Days

Label: 24555.73

L/S: 17k ✓
(Nett Value)