



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080302/Avh3e2
75 BRAS BASAH ROAD	Date:	18/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 1495D	Veh. Inspected	SNK 6484Z
Policy No.	-	Coverage	0
Claim No.	MT/1291177-002	Excess	\$0.00
Assign From	AMANDA CHOOI	Assign Date	20/08/2024

### 2. Vehicle Details

Make & Model	SUBARU FORESTER	C.C	1995
Engine No.	FB20YS14740	Year of Reg.	29/04/2023
Chassis No.	JF1SKEKL5NG078137	Colour	GREEN
Odometer	27612 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55 R18	BRIDGESTONE	6
L/H Front Tyre	225/55 R18	BRIDGESTONE	6
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	17/08/2024	Inspection Date	20/08/2024 (12:58)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days