

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24080304/ENP3M4
Date: 27/08/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ003007
Claimant Vehicle No :	SH7823D	Insured Vehicle No :	SNA8967L
Date of Loss:	15/08/2024	Nature of Claim:	TP
		Claim No:	M2404660

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7823D	Engine No:	G4LEJU045435
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVJU103294
Reg. Date:	03/07/2018 (Man. Year: 2018)	Odometer:	620178 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,413.00	3,694.68	1,718.32	31.74
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,900.00	1,430.00	470.00	24.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,325.00	5,136.68	2,188.32	29.87
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	7,325.00	4,100.00	3,225.00	44.03
+ GST 9.00/9.00% (S\$)	659.25	369.00	290.25	44.03
Nett Amount (S\$)	7,984.25	4,469.00	3,515.25	44.03

INSPECTION

Date of Assignment:	19/08/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/08/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2024)
Parts: 143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SH7823D)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER (BLUE-DRIVE) LH	Necessary	26.60 FL	*26.60 FL
2	1		*WING MIRROR LH	Broken	1,391.70 FL	*1,391.70 FL
3	1		*FRT DOOR LH	Dented	1,797.20 FL	*1,797.20 FL
4	1		*FRT DOOR OUTER HANDLE LH	Cut	234.80 FL	*234.80 FL
5	1		*FRT DOOR OUTER HANDLE COVER LH	Cut	10.50 FL	*10.50 FL
6	1		*FRT DOOR (COMFORTDELGRO) LH	Necessary	75.00 F	*75.00 F
7	1		*REAR DOOR (ZIG) APPS LH	Necessary	80.00 F	*80.00 F
8	1		*FRT FENDER ADV.STICKER LH	Necessary	100.00 F	*100.00 F
9	1		*FRT DOOR ADV.STICKER LH	Necessary	100.00 F	*100.00 F
10	1		*REAR DOOR ADV.STICKER LH	Necessary	100.00 F	*100.00 F
11	1		*REAR DOOR LH	Repair	2,147.90 FL	*- FL
Supplementary #1						
12	1		*FRT FENDER LH	Dented	588.80 FL	*588.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,652.50	4,504.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,239.50	809.92
Total Parts (\$\$)	5,413.00	3,694.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING - REAR DOOR LH ETC	New	800.00	570.00
2	SPRAY PAINTING - FRT FENDER LH ETC	New	1,000.00	840.00
3	TUFF KOTE	New	100.00	20.00
Gross Labour Cost (\$)			1,900.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >