

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24080305/KQP3E2

Date: 09/09/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003628654		
Claimant Vehicle No :	SKW1497S	Insured Vehicle No :	FBL6595Z		
Date of Loss:	15/08/2024	Nature of Claim:	TP	Claim No:	370599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW1497S	Engine No:	LEB5057984
Make & Model:	HONDA VEZEL HYBRID, 1.5 Z (A)	Chassis No:	RU31107976
Reg. Date:	20/10/2015 (Man. Year: 2015)	Odometer:	114609 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,637.44	1,048.96	588.48	35.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	880.00	1,540.00	63.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,057.44	1,928.96	2,128.48	52.46
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	4,057.44	1,550.00	2,507.44	61.80
+ GST 9.00/9.00% (S\$)	365.17	139.50	225.67	61.80
Nett Amount (S\$)	4,422.61	1,689.50	2,733.11	61.80

INSPECTION

Date of Assignment:	21/08/2024	
Date Inspected:	26/08/2024	Inspected At: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2024)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 Z (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW1497S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH ROCKER PANEL COVER	Cracked	433.20 FL	*433.20 FL
2	1		*RH ROCKER PANEL	Repair	380.20 FL	*- FL
3	1		*REAR DOOR RH	Repair	97.20 FL	*- FL
4	1		*SET REAR DOOR STICKER RH	Necessary	28.40 FL	*28.40 FL
5	1		*REAR FENDER INNER SHIELD RH	Serviceable	133.20 FL	*- FL
6	1		*REAR WHEEL ARCH RH	Dented	80.70 FL	*80.70 FL
7	1		*RIM	Dented	768.90 FL	*768.90 FL
8	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
9	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	2,021.80 1,311.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	384.36 262.24
					Total Parts (\$\$)	1,637.44 1,048.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	800.00	500.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	300.00
3	TO CHECK WIRING SYSTEM	New	100.00	0.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	0.00
5	WHEEL ALIGNMENT	New	100.00	60.00
6	TO REMOVE / REPLACE / REFIX / REAR LH WINDOW GLASS, MECHANISM & ETC TO NEW DOOR	New	300.00	0.00
7	TO REMOVE / REPLACE RIM	New	200.00	20.00
Gross Labour Cost (\$\$)			2,420.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >