



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 20/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHxebw Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU503575689		2ZRS110033	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SMX7709M ACC DATE:17/08/2024 TOW IN:19/08/2024 DATE-IN:19/08/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON: <i>PHV STICKER</i>						<i>50</i> 100.00
2	B	BP-LAB2	REPLACE & REPAIR FRT ACC AFFECTED AREAS					<i>20.80</i>
3	B	BP-RES2	RESpray JOB ON FRT ACC AFFECTED AREAS					633.6 1267.20
4	B	BP-LAB2	DRILL HOLE & INSTALL REAR REVERSE SENSOR					554.8 1049.60
5	B	BP-LAB2	CHECK LIGHTING & CONDUCT WATER LEAK TEST					158.40
6	B	BP-LAB2	REPLACE & INSTALL REAR TAILGATE GLASS					158.40
7	B	BP-LAB2	REPLACE & INSTALL REAR FIX GLASS					475.20
8	B	BP-LAB2	TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE					316.80 475.20
9	Z	BP-SLANT	SUPPLY SEALANT (NETT)					300.00
10	B	BP-LAB2	REMOVE & INSTALL REAR SEAT, CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR					633.60
11	B	BP-MECH2	REMOVE & INSTALL FUEL TANK					633.60
12	B	BP-MECH2	REMOVE & INSTALL REAR EXHAUST PIPE					316.80
13	S	BP-SUBLET	SUPPLY TYRE ? <i>plus</i>					380.00
							CUT <i>228</i>	
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts		Less Amount Due	
					Labour			
					Sublet			
					Lubrication/Fluid			
					Others			



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd	
		Document No. 0	3 Media Close #01-03/06 Singapore 138498	
		Document Date 20/08/2024	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU503575689	2ZRS110033	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	B	BP-MECH2 REPLACE TYRE & RIM ?				158.40
15	B	BP-MECH2 REPLACE & INSTALL REAR LH SUSPENSION SYS				633.60
		TEM				
16	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				158.40
17	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				158.40
18	B	BP-LAB2 REPLACE REAR LH ACCIDENT DAMAGED PARTS				4435.20
		STRAIGHTEN & ALIGN REAR LH ACCIDENT AFFECTED AREAS				
19	B	BP-RES2 RESPRAY JOB ON REAR LH ACCIDENT AFFECTED AREAS				3148.80
20	1	U52119-47962 COVER, FR BUMPER	1.00	799.30	30.00	559.51
21	2	U53112-47240 GRILLE, RADIATOR	1.00	237.60	30.00	166.32
22	3	U52159-47913 COVER, RR BUMPER	1.00	680.60	30.00	476.42
23	4	U52576-47040 RETAINER, RR BUMPER	1.00	177.50	30.00	124.25
24	5	U52575-47040 RETAINER, RR BUMPER	1.00	180.50	30.00	126.35
25	6	U52453-47010 GUARD, RR BUMPER	1.00	884.60	30.00	619.22
26	7	U52566-47900 FILLER, RR BUMPER	1.00	170.50	30.00	119.35
27	8	U52565-47900 FILLER, RR BUMPER	1.00	170.50	30.00	119.35
28	9	U52023-47030 REINFORCEMENT	1.00	512.40	30.00	358.68
29	0	K52161-0K040 PIECE, RR BUMPER	10.00	5.80	30.00	40.60
30	1	U52169-47020 COVER, RR BUMPER	1.00	21.40	30.00	14.98

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	Less
		Others	Amount Due

Customer Copy

Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128482, Tel no: 8631 1188

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 20/08/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU503575689	2ZRS110033	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
31	2	U75392-35220 RETAINER, OUTSIDE <i>an</i>	4.00	5.60	30.00	✓ 15.68
32	3	U52592-47040 SEAL, RR BUMPER <i>an</i>	1.00	122.30	30.00	✓ 85.61
33	4	U58307-47090 PANEL SUB-ASSY, BODY <i>bt</i>	1.00	1000.10	30.00	✓ 700.07
34	5	U58311-47130 PAN, RR FLOOR <i>repair</i>	1.00	886.30	30.00	X 620.41
35	6	U58316-47012 EXTENSION, RR FLOOR <i>? bt</i>	1.00	107.80	30.00	✓ 75.46
36	7	U66259-47010 COVER, RR BODY <i>? xan</i>	1.00	318.60	30.00	223.02
37	8	U58399-47030 COVER, FLOOR UNDER. <i>? xan</i>	1.00	334.70	30.00	234.29
38	9	U64716-47130 C0 COVER, DECK TRIM, RR <i>? xan</i>	1.00	174.20	30.00	121.94
39	0	U64997-47060 BOX, DECK FLOOR, LH <i>de</i>	1.00	433.30	30.00	✓ 303.31
40	1	U64993-47110 BOX, DECK FLOOR, RR <i>xan</i>	1.00	146.80	30.00	✓ 102.76
41	2	U64740-47190 C3 PANEL ASSY, DECK <i>? xan</i>	1.00	492.80	30.00	✓ 344.96
42	3	U61602-47160 PANEL SUB-ASSY. <i>? xan</i>	1.00	1339.40	30.00	✓ 937.58
43	4	U61622-47060 TROUGH, BACK DOOR <i>? bt</i>	1.00	142.90	30.00	✓ 100.03
44	5	U62940-12200 DUCT ASSY, QUARTER <i>de</i>	1.00	103.20	30.00	✓ 72.24
45	6	U77350-47050 LID ASSY, FUEL <i>xan</i>	1.00	234.60	30.00	✓ 164.22
46	7	U90269-06017 RIVET <i>xan</i>	2.00	5.40	30.00	✓ 7.56
47	8	U67005-47540 PANEL SUB-ASSY, BACK <i>bt</i>	1.00	1747.20	30.00	✓ 1223.04
48	9	U67881-47051 WEATHERSTRIP, BACK <i>cut</i>	1.00	515.40	30.00	✓ 360.78
49	0	U68105-47291 GLASS SUB-ASSY, BACK <i>an</i>	1.00	2298.70	30.00	✓ 1609.09
50	1	U56117-50140 DAM, WINDOW GLASS <i>an</i>	1.00	40.10	30.00	✓ 28.07

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Conv



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 20/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU503575689		2ZRS110033	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
51	2	U64801-47031 GLASS SUB-ASSY, BACK <i>br</i>			1.00	1052.00	30.00	✓ 736.40
52	3	U76801-47110 A1 GARNISH SUB-ASSY, <i>cr</i>			1.00	1283.40	30.00	✓ 898.38
53	4	U75403-48010 EMBLEM SUB-ASSY, <i>m</i>			1.00	99.40	30.00	✓ 69.58
54	5	U75441-47130 PLATE, LUGGAGE COMPT <i>m</i>			1.00	75.70	30.00	✓ 52.99
55	6	U75442-47130 PLATE, LUGGAGE COMPT <i>m</i>			1.00	75.70	30.00	✓ 52.99
56	7	U67750-47080 C0 BOARD ASSY, BACK <i>de</i>			1.00	358.40	30.00	✓ 250.88
57	8	U69350-47050 LOCK ASSY, BACK DOOR <i>7 X 11</i>			1.00	647.10	30.00	✓ 452.97
58	9	U68810-47061 HINGE ASSY, BACK <i>7 X 11</i>			1.00	84.90	30.00	✓ 59.43
59	0	U68810-47061 HINGE ASSY, BACK <i>7 X 11</i>			1.00	84.90	30.00	✓ 59.43
60	1	U81561-47153 LENS & BODY, RR <i>br</i>			1.00	677.90	30.00	✓ 474.53
61	2	U81498-47020 COVER, RR <i>son</i>			1.00	89.40	30.00	✓ 62.58
62	3	U81496-52020 GUIDE, RR <i>7 X 11</i>			2.00	3.60	30.00	✓ 5.04
63	4	U76817-26040 CLIP, BACK DOOR <i>m</i>			2.00	5.10	30.00	✓ 7.14
64	5	U81591-47011 LENS & BODY, RR <i>br</i>			1.00	777.30	30.00	✓ 544.11
65	6	T21000-20 SIKI 182010 SIKI TACK GO! (BLA <i>m</i>			3.00	108.00	30.00	✓ 226.80
66	7	T21000-22 SIKI 207. G+P ADHESIVE PRIMER <i>m</i>			2.00	200.00	30.00	✓ 280.00
67	8	SPC507-47001 16 BACK SENSOR WHITE PEARL SILVER <i>7 X 11</i>			1.00	169.60	30.00	✓ 118.72
68	9	U42611-47450 WHEEL, DISC <i>7. son</i>			1.00	2607.70	30.00	✓ 1825.39
69	0	U42602-47181 CAP SUB-ASSY, WHEEL <i>.cm</i>			1.00	293.60	30.00	✓ 205.52
70	1	U48530-80791 ABSORBER SET, SHOCK, <i>7. X 11</i>			1.00	176.20	30.00	✓ 123.34
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no : 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd	
		Document No. 0	3 Media Close #01-03/06 Singapore 138498	
		Document Date 20/08/2024	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU503575689	2ZRS110033	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
71	2	U48730-47010 ARM ASSY, RR ? 64	1.00	628.60	30.00	440.02
72	3	U42305-47050 CARRIER SUB-ASSY, RR ? 64	1.00	1317.20	30.00	922.04
73	4	U48780-47010 ARM ASSY, TRAILING ? 64	1.00	565.80	30.00	396.06
74	5	U48710-47010 ARM ASSY, RR ? 64	1.00	364.30	30.00	255.01
75	6	U48790-47010 ARM ASSY, UPR ? 64	1.00	641.00	30.00	448.70
76	7	U42450-76021 HUB & BRG ASSY, RR ? 64	1.00	824.00	30.00	576.80
77	8	T08826-08115 PANEL BONDING AD ? 64	1.00	267.20	30.00	187.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

For & on behalf of
Borneo Motors (Singapore) Pte Ltd

Customer's Signature
Please acknowledge receipt of vehicle

Charge Summary

Parts	19,787.04
Labour	18,600.00
Sublet	380.00
Lubrication/Fluid	0.00
Others	0.00

Total 38,767.04

GST 9.00% 3,489.03

Less 0.00

Amount Due 42,256.07