

(08/11/13) Wef

ASS. REC. BY:

REF:

CS/ICS24080313/Rvp3

2004
I27**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLN 448Pat Workshop m/s BARNBO MOOREof 2, PANDAN CRESCENTInsured: SMX 7709M ICS

Policy No.

Claims No. DMPC2401085H/ST

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

60K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLN 448PYr Regn: 2017 NIVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS Hybrid 1.8CVT c.c. 1798

Colour

WHITE

A/C: Insured / Std / Nil / NA

Sp. Reading

445795

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JTDKBFU503575689

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

1BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/08/24

D.O.I.

20/08/24

Survey held at

PANDAN C

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT & REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 40K

23/8/24 Submit preli report-revised fig \$22,464.34 check items \$8279.11

Date/Time, File Pass to?

☐
☐

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐
☐
☐
☐

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



Borneo Motors

nchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498
	Document No. 0	Work: 65703925
	Document Date 20/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU503575689	2ZRS110033	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SMX7709M ACC DATE:17/08/2024 TOW IN:19/08/2024 DATE-IN:19/08/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	B	BP-LAB2 REPLACE & REPAIR FRT ACC AFFECTED AREAS				1267.20
3	B	BP-RES2 RESPRAY JOB ON FRT ACC AFFECTED AREAS				1049.60
4	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				158.40
5	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				158.40
6	B	BP-LAB2 REPLACE & INSTALL REAR TAILGATE GLASS				475.20
7	B	BP-LAB2 REPLACE & INSTALL REAR FIX GLASS				316.80
8	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				475.20
9	Z	BP-SLANT SUPPLY SEALANT (NETT)				300.00
10	B	BP-LAB2 REMOVE & INSTALL REAR SEAT,CAROET,GARNISH AND TRIMMING TO ASSIST REPAIR				633.60
11	B	BP-MECH2 REMOVE & INSTALL FUEL TANK				633.60
12	B	BP-MECH2 REMOVE & INSTALL REAR EXHAUST PIPE				316.80
13	S	BP-SUBLET SUPPLY TYRE ? <i>phche</i>				380.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 20/08/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU503575689	2ZRS110033	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	B	BP-MECH2 REPLACE TYRE & RIM ?				158.40
15	B	BP-MECH2 REPLACE & INSTALL REAR LH SUSPENSION SYS TEM				633.60
16	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				158.40
17	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				158.40
18	B	BP-LAB2 REPLACE REAR LH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR LH ACCIDENT AFFECTED AREAS				443.52
19	B	BP-RES2 RESPRAY JOB ON REAR LH ACCIDENT AFFECTED AREAS				3148.8
20	1	U52119-47962 COVER, FR BUMPER	1.00	799.30	30.00	559.51
21	2	U53112-47240 GRILLE, RADIATOR	1.00	237.60	30.00	166.32
22	3	U52159-47913 COVER, RR BUMPER	1.00	680.60	30.00	476.42
23	4	U52576-47040 RETAINER, RR BUMPER	1.00	177.50	30.00	124.25
24	5	U52575-47040 RETAINER, RR BUMPER	1.00	180.50	30.00	126.35
25	6	U52453-47010 GUARD, RR BUMPER	1.00	884.60	30.00	619.22
26	7	U52566-47900 FILLER, RR BUMPER	1.00	170.50	30.00	119.35
27	8	U52565-47900 FILLER, RR BUMPER	1.00	170.50	30.00	119.35
28	9	U52023-47030 REINFORCEMENT	1.00	512.40	30.00	358.68
29	0	K52161-0K040 PIECE, RR BUMPER	10.00	5.80	30.00	40.60
30	1	U52169-47020 COVER, RR BUMPER	1.00	21.40	30.00	14.98

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 20/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU503575689	2ZRS110033	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
31	2	U75392-35220 RETAINER, OUTSIDE <i>W</i>	4.00	5.60	30.00	15.68
32	3	U52592-47040 SEAL, RR BUMPER <i>W</i>	1.00	122.30	30.00	85.61
33	4	U58307-47090 PANEL SUB-ASSY, BODY <i>W</i>	1.00	1000.10	30.00	700.07
34	5	U58311-47130 PAN, RR FLOOR <i>repair</i>	1.00	886.30	30.00	620.41
35	6	U58316-47012 EXTENSION, RR FLOOR <i>?</i>	1.00	107.80	30.00	75.46
36	7	U66259-47010 COVER, RR BODY <i>?</i>	1.00	318.60	30.00	223.02
37	8	U58399-47030 COVER, FLOOR UNDER <i>?</i>	1.00	334.70	30.00	234.29
38	9	U64716-47130 C0 COVER, DECK TRIM, RR <i>?</i>	1.00	174.20	30.00	121.94
39	0	U64997-47060 BOX, DECK FLOOR, LH <i>de</i>	1.00	433.30	30.00	303.31
40	1	U64993-47110 BOX, DECK FLOOR, RR <i>X</i>	1.00	146.80	30.00	102.76
41	2	U64740-47190 C3 PANEL ASSY, DECK <i>?</i>	1.00	492.80	30.00	344.96
42	3	U61602-47160 PANEL SUB-ASSY <i>?</i>	1.00	1339.40	30.00	937.58
43	4	U61622-47060 TROUGH, BACK DOOR <i>?</i>	1.00	142.90	30.00	100.03
44	5	U62940-12200 DUCT ASSY, QUARTER <i>de</i>	1.00	103.20	30.00	72.24
45	6	U77350-47050 LID ASSY, FUEL <i>X</i>	1.00	234.60	30.00	164.22
46	7	U90269-06017 RIVET <i>X</i>	2.00	5.40	30.00	7.56
47	8	U67005-47540 PANEL SUB-ASSY, BACK <i>W</i>	1.00	1747.20	30.00	1223.04
48	9	U67881-47051 WEATHERSTRIP, BACK <i>cut</i>	1.00	515.40	30.00	360.78
49	0	U68105-47291 GLASS SUB-ASSY, BACK <i>W</i>	1.00	2298.70	30.00	1609.09
50	1	U56117-50140 DAM, WINDOW GLASS <i>X</i>	1.00	40.10	30.00	28.07

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 20/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU503575689	2ZRS110033	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
51	2	U64801-47031 GLASS SUB-ASSY, BACK <i>bro ✓</i>	1.00	1052.00	30.00	736.40
52	3	U76801-47110 A1 GARNISH SUB-ASSY, <i>ca ✓</i>	1.00	1283.40	30.00	898.38
53	4	U75403-48010 EMBLEM SUB-ASSY, <i>m ✓</i>	1.00	99.40	30.00	69.58
54	5	U75441-47130 PLATE, LUGGAGE COMPT <i>m ✓</i>	1.00	75.70	30.00	52.99
55	6	U75442-47130 PLATE, LUGGAGE COMPT <i>m ✓</i>	1.00	75.70	30.00	52.99
56	7	U67750-47080 C0 BOARD ASSY, BACK <i>de ✓</i>	1.00	358.40	30.00	250.88
57	8	U69350-47050 LOCK ASSY, BACK DOOR <i>?</i>	1.00	647.10	30.00	452.97
58	9	U68810-47061 HINGE ASSY, BACK <i>?</i>	1.00	84.90	30.00	59.43
59	0	U68810-47061 HINGE ASSY, BACK <i>?</i>	1.00	84.90	30.00	59.43
60	1	U81561-47153 LENS & BODY, RR <i>bro ✓</i>	1.00	677.90	30.00	474.53
61	2	U81498-47020 COVER, RR <i>sa ✓</i>	1.00	89.40	30.00	62.58
62	3	U81496-52020 GUIDE, RR <i>?</i>	2.00	3.60	30.00	5.04
63	4	U76817-26040 CLIP, BACK DOOR <i>m ✓</i>	2.00	5.10	30.00	7.14
64	5	U81591-47011 LENS & BODY, RR <i>bro ✓</i>	1.00	777.30	30.00	544.11
65	6	T21000-20 SIKI 182010 SIKI TACK GO! (BLA <i>m ✓</i>	3.00	108.00	30.00	226.80
66	7	T21000-22 SIKI 207. G+P ADHESIVE PRIMER <i>m ✓</i>	2.00	200.00	30.00	280.00
67	8	SPC507-47001 16 BACK SENSOR WHITE PEARL SILVER <i>?</i>	1.00	169.60	30.00	118.72
68	9	U42611-47450 WHEEL, DISC <i>?</i>	1.00	2607.70	30.00	1825.39
69	0	U42602-47181 CAP SUB-ASSY, WHEEL <i>?</i>	1.00	293.60	30.00	205.52
70	1	U48530-80791 ABSORBER SET, SHOCK, <i>?</i>	1.00	176.20	30.00	123.34

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 20/08/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0448P	0	32385	67/TP/SLU0448P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU503575689	2ZRS110033	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
71	2	U48730-47010 ARM ASSY, RR ?	1.00	628.60	30.00	440.02
72	3	U42305-47050 CARRIER SUB-ASSY, RR ?	1.00	1317.20	30.00	922.04
73	4	U48780-47010 ARM ASSY, TRAILING, ?	1.00	565.80	30.00	396.06
74	5	U48710-47010 ARM ASSY, RR ?	1.00	364.30	30.00	255.01
75	6	U48790-47010 ARM ASSY, UPR ?	1.00	641.00	30.00	448.70
76	7	U42450-76021 HUB & BRG ASSY, RR ?	1.00	824.00	30.00	576.80
77	8	T08826-08115 PANEL BONDING AD ?	1.00	267.20	30.00	187.04

*From
4p 900m68
14 days
20/08/24
Resy & pmt*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 38,767.04
	Please acknowledge receipt of vehicle	Parts 19,787.04 Labour 18,600.00 Sublet 380.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00% 3,489.03
		Less 0.00	Amount Due 42,256.07

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLU448P
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	2ZRS110033
Chassis No.:	JTDKB3FU503575689
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	21 Nov 2017
First Registration Date:	21 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2027
PARF Rebate Amount:	\$3,517.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,996.00
COE Rebate Amount:	\$16,248.00
Total Rebate Amount:	\$19,765.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 20 Aug 2024

OK