

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Paul Chew Nam Seng	Cust No/Name	/Mr Paul Chew Nam Seng
156 PASIR RIS STREET 13	Reg No/Reg Date	SJY7379L / 10/03/2020
#07-37	Date In/Mileage	02/09/2024/ 63919
SINGAPORE 510156	Chassis No	GF7W0700353
Contact No Mobile: 94501278	Engine No	4J11CC5723
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	02/09/2024/ 14:18	REN	979 / Renemer Ramirez Bag	26201
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT					
ACCIDENT ON 17/08/2024 ALONG EXIT OF TPE TO UPPER CHANGI RD NORTH					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT VEHICLE					
TP#: SKP9844H TP INS: CHINA TAIPING					
A 10028901					280.00
TO CARRY OUT DIAGNOSTIC CHECK ON MUT AND CLEAR TROUBLE CODE					
A 90000001					80.00
TO CHECK WIRING AND ELECTRICAL SYSTEM					
E PNT88000					320.00
TO REMOVE & RE-INSTALL TAILGATE					
TO REMOVE & REPLACE DAMS,FASTENER & STOPPERS					
E PNT88000					320.00
TO REMOVE & RE-INSTALL FLOOR BOARDS,TRIMS & CARPETS TO FACILITATE					
REPAIR ON REAR ACCIDENT AFFECTED AREAS					
E PNT88000					320.00
TO TRANSFER TAILGATE COMPONENTS & MECHANISM					
E PNT88000					2560.00
TO REPLACE EMBLEM,LOGO,TAILGATE PANEL,REAR BUMPER,CLIPS,					
LH SIDE BRACKET,EXTENSION REAR BUMPER & CLIPS,BUZZER,ANTENNA,					
LH REINFORCEMENT,ETC -TO CUT & WELD REAR END PANEL					
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS					
E PNT98000					1650.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					
(TAILGATE PANEL,REAR BUMPER,REAR END PANEL)					
E PNT88000					80.00
TO CHECK,TEST & REFIT REVERSE SENSORS					
E PNT88000					220.00
TO SUPPLY ONE SET REVERSE SENSOR					
M SUNDRY					80.00
TO APPLY GLASS SEALANT ON NEW TAILGATE GLASS					
M SUNDRY					160.00
TO APPLY BODY SEALANT ON NEW TAILGATE PANEL & REAR END PANEL					

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Paul Chew Nam Seng	Cust No/Name /Mr Paul Chew Nam Seng
156 PASIR RIS STREET 13	Reg No/Reg Date SJY7379L / 10/03/2020
#07-37	Date In/Mileage 02/09/2024/ 63919
SINGAPORE 510156	Chassis No GF7W0700353
Contact No Mobile: 94501278	Engine No 4J11CC5723
	Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	02/09/2024/ 14:18	REN	979 / Renemer Ramirez Bag	26201
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SUNDRY	TO APPLY ANTI-CORROSION ON NEW TAILGATE PANEL & REAR END PANEL				160.00
M SUNDRY	TO SUPPLY MIVEC EMBLEM				50.00
M SUNDRY	TO SUPPLY C&C BADGE				50.00
M SUNDRY	SUNDRIES				20.00
Z TEXT	FINALIZATION				
	NO. OF TOTAL REPAIR DAYS - 7 DAYS				
	ATTENTION TO MR. STEVE CHEN (LKK)				
X DAM, TAILGATE, UPR		1.00	13.00	00.00	13.00
X DAM, TAILGATE SIDE		2.00	34.00	00.00	68.00
X DAM, TAILGATE, LWR		1.00	25.00	00.00	25.00
X FASTENER, WINDSHIELD		4.00	8.00	00.00	32.00
X STOPPER, WINDSHIELD GLASS		2.00	4.00	00.00	8.00
X MARK, THREE-DIA		1.00	64.00	00.00	64.00
X MARK, OUTLANDER		1.00	120.00	00.00	120.00
X PANEL ASSY, TAILGATE		1.00	1043.00	00.00	1043.00
X FACE, RR BUMPER		1.00	872.00	00.00	872.00
X CLIP, ENG ROOM COVER		5.00	2.00	00.00	10.00
X CLIP, FR BUMPER		5.00	4.00	00.00	20.00
X BRKT, R/BMPR FACE SIDE, LH		1.00	20.00	00.00	20.00
X EXTENSION, RR BUMPER		1.00	376.00	00.00	376.00
M CLIP, EXTENSION, RR BUMPER		2.00	26.00	00.00	52.00
M BUZZER, KEYLESS OPERATION, RR		1.00	96.00	00.00	96.00
M ANT, KEYLESS OPERATION, RR		1.00	101.00	00.00	101.00
M REINFORCEMENT, RR BUMPER, LH		1.00	99.00	00.00	99.00
M PANEL, RR END		1.00	342.00	00.00	342.00

Confirm & accepted by

9% GST on **Nett 9,711.00**
873.99

Total Payable 10,584.99

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.