



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2505307

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/08/2025
Reference CD/CTI24080318/Tma3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMB 143G
Insured Veh. SLA 7778X
Claim No. SNM24D204704
Policy No. DMPCSNA00068302302
Accident Date 09/04/2024
Inspection Date 20/08/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CD/CTI24080318/Tma3q2(N)	
			Date: 12/08/2025	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 7778X	Veh. Inspected	SMB 143G
	Policy No.	DMPCSNA00068302302	Coverage (\$)	0.00
	Claim No.	SNM24D204704	Excess (\$)	0.00
	Assign From		Assign Date	20/08/2024
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CITARO O530	c.c	10815
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WEB62808323120698	Colour	MULTI COLOUR
	Odometer	955120 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
	L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
	L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/04/2024	Inspection Date	20/08/2024
	Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 143G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	TO REPAIR SEE LABOUR		
	BUMPER REAR RH FOR MB CITARO O530		837.84	-
			837.84	-
	<u>LABOUR</u>			
	TO REPAIR REAR RHS PORTION.INCLUSIVE OF THE REPAIR OF BUMPER REAR RH FOR MB CITARO O530. PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		530.00	265.00
			616.00	446.00
			1,146.00	711.00
GRAND TOTAL			1,983.84	711.00
RECOMMENDED COST OF REPAIRS				711.00

Report Ref No. CD/CT124080318/Tma3q2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



HO LEONG CHUAN

Automotive Assessor



DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.




PHOTOGRAPHS FOR VEHICLE NO. : SMB 143G




PHOTOGRAPHS FOR VEHICLE NO. : SMB 143G



PHOTOGRAPHS FOR VEHICLE NO. : SMB 143G



PHOTOGRAPHS FOR VEHICLE NO. : SMB 143G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SMB 143G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SMB 143G

