



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/08/2024

User ID : choonhwee03

Section A - Accident Details	
Registration Number	SMB143G
Case Reference Number	BUS/04/24/7009
Registration Date	3/14/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	CITARO O530
Name of Driver	Tay Tze Siong
Type of Accident	Side Swipe
Accident Date and Time	4/9/2024 2:10 PM
Accident Reported Date and Time	4/9/2024 4:23 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB143G - SCRATCHES ON RIGHT REAR PORTION TP: SLA7778X - SCRATCHES ON LEFT FRONT PORTION - CHINA TAIPING
Prepared Date and Time	8/19/2024 11:09 AM
Chassis Number	WEB62808323120698
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,146.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1 DAY
Prepared / Adjusted By	Jeong Choon Hwee	Taufikh
ARC / Surveyor Sign Off Date	19/08/2024 11:17 AM	20/8/24
Signature		 <i>taufikh</i>
Remarks		Taufikh 97495749 WP 20/8/24 P/P RESURVEY AFTER REPAIR taufikh@LKKauto.com

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/08/2024

User ID : choonhwee03

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REPAIR REAR RHS PORTION				\$530.00				265	
Total Labour				\$530.00					
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$616.00				446	
Total Spray Painting & Panel Beating				\$616.00					
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009909	BODY RH		BUMPER:REAR,RH,FOR MB CITARO O530	1.00	\$837.84	100.00	\$0.00	Repair	XR
Total					\$837.84		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									