

SMRT Accident Vehicle Repair Estimates

Section A - Accident Details				
Registration Number	SMB143G			
Case Reference Number	BUS/04/24/7009			
Registration Date	3/14/2011			
Company Type	SMRT Buses Ltd			
Make	MERCEDES			
Model	CITARO O530			
Name of Driver	Tay Tze Siong			
Type of Accident	Side Swipe			
Accident Date and Time	4/9/2024 2:10 PM			
Accident Reported Date and Time	4/9/2024 4:23 PM			
Is Surveyor Required?	No			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number				
Special Instruction to ARC,if any	SMB143G - SCRATCHES ON RIGHT REAR PORTION TP: SLA7778X - SCRATCHES ON LEFT FRONT PORTION - CHINA TAIPING			
Prepared Date and Time	8/19/2024 11:09 AM			
Chassis Number	WEB62808323120698			
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Rep	pair Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$530.00	\$0.00			
Total Spray Cost	\$616.00	\$0.00			
Total Spare Part Cost	\$0.00	\$0.00			
Total Other Cost	\$0.00	\$0.00			
TOTAL COST	\$1,146.00	\$0.00			
Lump Sum Total	\$0.00	\$0.00			
Number of Repair Days	2.0				
Prepared / Adjusted By	Jeong Choon Hwee				
ARC / Surveyor Sign Off Date	19/08/2024 11:17 AM				
Signature	×	×			
Remarks					

Section C - Quotation and Accident Invoice Details						
Quotation Number		Invoice Number				
Quotation Date		Invoice Date				
Invoice Amount		Prepared Date				

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 19/08/2024
User ID : choonhwee03



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

: choonhwee03

FAX Number : 63685592

User ID

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 19/08/2024

			Section	on D - Detai	Is of Repair E	stimates			
Part 1 - Labou	ır Works								
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REPAIR REAR RHS PORTION			\$530.00						
Total Labour			\$530.00						
Part 2 - Spray	Painting & Pa	nel Beating Rela	ted Works						
Job Scope (Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$616.00						
Total Spray Painting & Panel Beating			\$616.00						
Part 3 - Other	Costs - Accide	ent and Acciden	t Repair Related Expens	se					
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare	Parts / Materia	al Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009909	BODY RH		BUMPER:REAR,RH,FOR MB CITARO 0530	1.00	\$837.84	100.00	\$0.00	Repair	
Total					\$837.84		\$0.00		
Added Spare	Parts / Materia	I Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

Total