

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 19.08.2024
 VEH NO : SMN2262U
 MODEL : Honda Jazz
 D O A : 17.08.2024
 YR REF : SMH6312P

Xiao Tony

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMN2262U (HONDA JAZZ)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>	
NO	LIST ITEMS			
1	Front Bumper <i>Behind</i>	1	594.70	✓
2	Front Bumper Side Holder	1	23.90	+
3	Head Lamp - RH <i>{ new</i>	1	1,322.30	+
4	Head Lamp Lower Bracket - RH	1	58.40	+
5	Front Fender - RH <i>Dented</i>	1	368.20	✓
6	Front Fender Inner Shield - RH <i>Behind</i>	1	128.20	✓
7	Front Fender Glass - RH <i>cut</i>	1	280.60	✓
8	Front Fender Glass Moulding - RH <i>new</i>	1	42.10	✓
9	Front Door - RH <i>Dented</i>	1	965.80	✓
10	Front Door Lock - RH <i>Damaged</i>	1	248.30	✓
11	Front Door Weatherstripe - RH <i>new</i>	1	178.50	+
12	Front Door Hinges - RH <i>{ new</i>	2	174.40	+
13	Front Door Checker - RH	1	68.50	+
14	Front Door Inner Trim Board - RH <i>cut</i>	1	547.90	✓
15	Front Door Glass - RH <i>new</i>	1	421.90	+
16	Front Door Glass Outer Moulding - RH <i>Behind</i>	1	105.90	✓
17	Front Door Glass Regulator Gear - RH <i>and</i>	1	238.70	+
18	Front Door Glass Regulator Motor - RH <i>new</i>	1	320.40	+
19	Front Door Channel - RH <i>But</i>	1	92.80	✓
20	Front Door Outer Handle - RH <i>new</i>	1	140.60	+
21	Front Door Wing Mirror - RH <i>and</i>	1	589.70	✓
22	Front Door Wing Mirror Cover - RH <i>missing</i>	1	86.30	✓
23	Rocker Panel <i>Repair</i>	1	396.40	+
24	Door Centre Pillar <i>Dented</i>	1	750.90	✓
25	Rear Door - RH <i>Dented</i>	1	980.20	✓
26	Rear Door Lock - RH <i>new</i>	1	251.40	+
27	Rear Door Weatherstripe - RH <i>new</i>	1	170.90	+
28	Rear Door Vertical Weatherstripe - RH <i>cut</i>	1	108.90	✓

RE : ESTIMATE FOR ACCIDENT REPAIR SMN2262U (HONDA JAZZ)

29	Rear Door Inner Trim Board - RH	1	495.80	X
30	Rear Door Glass Regulator Gear - RH	1	245.10	X
31	Rear Door Glass Regulator Motor - RH	1	330.50	X
32	Front Lower Arm Bent	1	390.60	✓
33	Front Shock Absorber New	1	317.50	X
34	Front Knuckle Arm New	1	381.90	✓
35	Front Wheel Hub C/w Bearing New	1	238.60	✓
36	Steering Rack & Pinion New	1	1,890.50	X

Less 20%

13,947.30

(2,789.46)

\$ 11,157.84

S/NETT ITEMS

1	Front Bumper Clips New	1 set	30.00	✓
2	Front Fender Inner Shield Clips New	1 set	30.00	✓
3	Front Fender Glass Solar Film New	1	100.00 60	
4	Front Wheel Rim Cut	1	700.00 450	
5	Front Tyre New	1	280.00	X
6	Front Door Inner Trim Board Clips New	1 set	30.00	✓
7	Front Door Black Tape New	1	60.00	✓
8	Rocker Panel Sealant New	1	60.00	+
9	Centre Door Pillar Sealant New	1	60.00	✓
10	Rear Door Inner Trim Board Clips New	1 set	30.00	X
11	Rear Door Black Tape New	1	60.00	✓
			\$ 1,440.00	

Total Parts

\$ 12,597.84

LABOUR CHARGE

1	To knocking & pull out RH side portion & renew above parts	\$	2,000.00 1400
2	To putty & spray up paint works	\$	1,600.00 1300
3	To check wiring	\$	50.00 30
4	To apply tuff coat	\$	150.00 120
5	To transfer front door fittings	\$	150.00 80
6	To transfer rear door fittings	\$	150.00 80
8	To remove upholstery & front driver seat	\$	280.00 150
9	To perform wheel alignment	\$	150.00 80

RE : ESTIMATE FOR ACCIDENT REPAIR SMN2262U (HONDA JAZZ)

10	To remove front undercarriage		\$	350.00 <i>wo</i>
11	To remove steering rack & pinion	3440	\$	180.00 <i>x</i>
Total Labour			\$	5,060.00
Grand Total			\$	17,657.84

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 9932.24

L/s : 7950

10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: