

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080321/UUA3Q2**Date:** 02/12/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210050660
Claimant Vehicle No : SLC1408T **Insured Vehicle No :** SDK1212T
 Date of Loss: 30/06/2024 Nature of Claim: TP Claim No: 9090958972SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC1408T**
 Make & Model: HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A) Engine No: G4FMMU048069
 Reg. Date: 29/07/2021 (Man. Year: 2021) Chassis No: KMHLN41ETNU213037
 Colour: White Odometer: 49571 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,368.40	0.00	6,368.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	450.00	1,900.00	80.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,718.40	450.00	8,268.40	94.84
+ GST 9.00/9.00% (S\$)	784.66	40.50	744.16	94.84
Nett Amount (S\$)	9,503.06	490.50	9,012.56	94.84
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		717.75		

INSPECTION

Date of Assignment: 02/09/2024
 Date Inspected: 02/09/2024 Inspected At: SPEEDWERKZ PTE LTD (Autobay) (HQ)
 1 KAKI BUKIT AVENUE 6 #01-73
 Singapore 417883
 Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Not Necessary	1,904.70 FL	*- FL
2	1		*FRONT DOOR WINDOW OUTER GLASS MOULDING RH	Not Necessary	161.40 FL	*- FL
3	1		*FRONT DOOR BLACK STICKER RH	Not Necessary	51.80 FL	*- FL
4	1		*FRONT DOOR SIDE MIRROR ASSEMBLY RH	Repair	1,451.50 FL	*- FL
5	1		*FRONT DOOR SIDE MIRROR COVER RH	Serviceable	233.70 FL	*- FL
6	1		*FRONT FENDER RH	Not Necessary	801.40 FL	*- FL
7	1		*FRONT RIN RH	Repair	866.70 FL	*- FL
8	1		*FRONT RIN CENTRE CAP RH	Repair	112.30 FL	*- FL
9	1		*FRONT WHEEL BEARING AND HUB RH	Not Necessary	456.10 FL	*- FL
10	1		*FRONT KNUCKLE ARM RH	Not Necessary	525.20 FL	*- FL
11	1		*FRONT LOWER ARM RH	Not Necessary	456.80 FL	*- FL
12	1		*FRONT SHOCK ABSORBER RH	Not Necessary	388.90 FL	*- FL
13	1		*FRONT DOOR TRIMBOARD CLIPS	Not Necessary	60.00 FS	*- FS
14	1		*FRONT RH TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,850.50	0.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,482.10	0.00
Total Parts (\$\$)	6,368.40	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE AND TRANSFER FRONT DOOR RH FITTINGS TO NEW	New	100.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	90.00	0.00
4	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE	New	250.00	0.00
5	TO REMOVE AND REPLACE FRONT TYRE AND BALANCING	New	80.00	0.00
6	TO PROVIDE LABOUR WORKMANSHIP	New	800.00	130.00
7	TO SPRAY PAINT ON AFFECTED PANELS INCLUDING WRAP STICKER	New	900.00	300.00
8	RUST PROOFING	New	80.00	0.00
Gross Labour Cost (\$\$)			2,350.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >