

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CD/A1624060321/Uua3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 1408T

at Workshop m/s speed nether

of _____

Insured: SDC 12124

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$100k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: 1.9.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 8226

Vehicle: IN / OUT

21436366

Veh No: SLC 1408T Yr Regn: 29/07/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Hyundai CN7A Vette.c 1598

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 49571 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLN41ETNU 213037

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 30/06/24 D.O.I. 2/9/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 H 0/5 w.y mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22p 14h.

4/9/24 wry sudan
7/7 8 450 in hand Raymond

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format: _____

Lump Sum / I.B.I: (\$)

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

Not Allowed
in
menu
2/9/24
N/P = 450
1 day

VEHICLE NUMBER: SLC1408T

MAKE & MODEL: HYUNDAI AVANTE CN7

FRONT DOOR RH	11	\$1,904.70	X
FRONT DOOR WINDOW OUTER GLASS MOULDING RH	11	\$161.40	X
FRONT DOOR BLACK STICKER RH	11	\$51.80	X
FRONT DOOR SIDE MIRROR ASSEMBLY RH	R	\$1,451.50	X
FRONT DOOR SIDE MIRROR COVER RH	SVC	\$233.70	X
FRONT FENDER RH	11	\$801.40	X
FRONT RIM RH	R	\$866.70	X
FRONT RIM CENTRE CAP RH	R	\$112.30	X
FRONT WHEEL BEARING AND HUB RH	11	\$456.10	X
FRONT KNUCKLE ARM RH	11	\$525.20	X
FRONT LOWER ARM RH	11	\$456.80	X
FRONT SHOCK ABSORBER RH	11	\$388.90	X
		\$7,410.50	
	Less 20%	\$1,482.10	
		\$5,928.40	
FRONT DOOR TRIMBOARD CLIPS	NN	\$60.00	X
FRONT RH TYRE	NN	\$380.00	X
		\$440.00	
TO CHECK WIRING		\$50.00	20
TO REMOVE AND TRANSFER FRONT DOOR RH FITTINGS TO NEW	11	\$100.00	X
TO CONDUCT WHEEL ALIGNMENT	11	\$90.00	X
TO REMOVE AND REPLACE FRONT UNDERCARRIAGE	11	\$250.00	X
TO REMOVE AND REPLACE FRONT TYRE AND BALANCING	11	\$80.00	X
TO PROVIDE LABOUR, WORKMANSHIP		\$800.00	130
TO SPRAY PAINT ON AFFECTED PANELS <i>including wrap sticker</i>		\$900.00	300
RUST PROOFING	11	\$80.00	X
		\$2,350.00	
Total		\$8,718.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: