

Regnant Automotive Pte Ltd

Address: 53 Ubi Ave 1 #01-09 Paya Ubi Industrial Park (S)408934 Tel: 8088 0109 UEN No.: 202403813N

VEHICLE NO SNL 1701A MAKE MODEL TOYOTA NOAH

REFERENCE

DOA

19.08.2024

CLAIM TYPE

ATTN: MOTOR CLAIMS DEPARTMENT

THIRD PARTY CLAIM

PARTS	QTY	LIST PRICE (5)	
TAILGATE X P	1	\$ 3,263.00	
TAILGATE WEATHERSTRIP 🗸	1	\$ 590.00	
REAR EMBLEM "LOGO" / M/C	1	\$ 150.00	
REAR EMBLEM "NOAH"	1	\$ 120.00	
REAR EMBLEM "HYBRID SYNERGY DRIVE" - 1	1	\$ 140.00	
REAR PANEL X K	1	\$ 1,400.00	
REAR BUMPER / OLF	1	\$ 890.00	797/
REAR BUMPER SIDE RETAINER LH	1	\$ 65.00	
REAR BUMPER SIDE RETAINER RH	1	\$ 65.00	
REAR BUMPER BRACKET RH X	1	\$ 50.00	
REAR BUMPER BRACKET LH Y	1	\$ 50.00	
REAR TOW COVER X	1	\$ 50.00	
REAR REFELCTOR RH 💢	1	\$ 80.00	
REAR REFELCTOR LH X	1	\$ 80.00	
		\$ 6,993.00	
	LESS 25%	\$ 1,748.25	
	TOTAL	\$ 5,244.75	

PECIAL METERS AND	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER CLIP / M	1 SET	\$ 100.00	
REAR REVERSE SENSOR	1 SET	\$ 500.00	
,		\$ 600.00	

DARSON CONTRACTOR OF THE PARTY		IIIS	TPRICE (S)	REMARKS
	BALANCE B/F	\$	5,844.75	
CHECK REAR WIRING AND LIGHTING SYSTEM		\$	150.00	30
TRANSFER PARTS, ATTACHMENT FROM OLD TO NEW		\$	300.00	X
REMOVE AND RENEW REAR REVERSE SENSOR		\$	120.00	30
REMOVE, REFIT REAR LINING, TRIM AND GARNISH		\$	200.00	X
DIAGNOIS CHECK AND CLEAR FAULT CODE		\$	200.00	X
PANEL BEATING ON AFFECTED AREAS AND RENEW PART		\$	800.00	300
SPRAY PAINTING ON AFFECTED AREAS		\$	800.00	400
	SUBTOTAL	\$	2,570.00	
	GRAND TOTAL	\$	8,414.75	

Steve (LKK)
2/9/24, 10.30an

M. IL

L/S

M. Al M.

3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: