

REF:

ASSIGNMENT

From: _____ Date: _____
 Estin: ~~Est~~ ^{Est} _____
 OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV
 To In: _____ Vehicle No: _____
 at W/O: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)

Veh No: SLA 1688L Yr Regn: 2007, July
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Camry C.D. 2362
 Colour: Silver A/C: Insured / Std / NI / N.A.
 Sp. Reading: 169238 T/Radio: Insured / Std / NI / N.A.
 Eng/No: _____
 C/No: MRO53BK4007014210
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modif: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: 215/55R17
 R: 215/55R17

Remark: Veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 21/08/24
 Survey held at HD Perfect
 Des. of Damages: Frt Rear / O/S / WS / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP III
	COE Expiry : 15/07/2027.
	Estimate given during : Yes (✓) 1st Survey : No ()
	MV 34K (Depreciation @ 11.5K x 3yr PV: 16K ≈ 34K) Nett: 18K.
	957I.

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Form No: _____
 Report Form No: _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Inve (\$ _____)

Survey Fee:

Transportation:	_____
3 + RS:	_____
Photos	_____
Others	_____


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 19.08.2024

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLA1688L**
MODEL : **TOYOTA CAMRY**
DATE OF ACCIDENT : 19.08.2024
TIME OF ACCIDENT : 09:20 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Repld</i>	1	\$ 520.00	\$ 520.00
2	FRONT BUMPER BOTTOM COVER GARNISH <i>AT</i>	2	\$ 275.00	\$ 550.00
3	FRONT BUMPER FOGLAMP <i>new</i>	2	\$ 215.00	\$ 430.00
4	FRONT BUMPER FOGLAMP COVER <i>culd</i>	2	\$ 95.00	\$ 190.00
5	FRONT BUMPER TOW HOOK COVER <i>new</i>	1	\$ 30.00	\$ 30.00
6	FRONT BUMPER GRILLE (UPPER) <i>culd</i>	1	\$ 570.00	\$ 570.00
7	FRONT BUMPER GRILLE (LOWER) <i>culd</i>	1	\$ 158.00	\$ 158.00
8	FRONT BUMPER GRILLE LOGO <i>new</i>	1	\$ 65.00	\$ 65.00
9	FRONT BUMPER RETAINER <i>new</i>	2	\$ 85.00	\$ 170.00
10	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 465.00	\$ 465.00
11	FRONT BUMPER SPONGE <i>culd</i>	1	\$ 140.00	\$ 140.00
12	HEADLAMP <i>culd</i>	2	\$ 2,596.00	\$ 5,192.00
13	FRONT FENDER INNER COWLING <i>new</i>	2	\$ 175.00	\$ 350.00
14	BONNET <i>Dented</i>	1	\$ 1,425.00	\$ 1,425.00
15	BONNET DAMPER <i>new</i>	2	\$ 130.00	\$ 260.00
16	BONNET INSULATOR <i>new</i>	1	\$ 505.00	\$ 505.00
17	BONNET HINGE <i>new</i>	2	\$ 70.00	\$ 140.00
18	BONNET RUBBER <i>new</i>	1	\$ 75.00	\$ 75.00
19	BONNET LOCK <i>new</i>	1	\$ 150.00	\$ 150.00
20	BONNET STOPPER <i>new</i>	2	\$ 20.00	\$ 40.00
21	BRACE PANEL <i>Dented</i>	1	\$ 125.00	\$ 125.00

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLA1688L**
 MODEL : **TOYOTA CAMRY**
 DATE OF ACCIDENT : 19.08.2024
 TIME OF ACCIDENT : 09:20 HOURS

22	RADIATOR SUPPORT PANEL <i>Buckled</i>	1	\$ 1,035.00	\$ 1,035.00	✓
23	AIR DUCT <i>ren</i>	1	\$ 185.00	\$ 185.00	+
24	HORN <i>Ren</i>	2	\$ 120.00	\$ 240.00	+
25	AIRCON CONDENSOR <i>Dented</i>	1	\$ 1,620.00	\$ 1,620.00	✓
26	AIRCON PIPE <i>Ren</i>	1	\$ 387.00	\$ 387.00	+
27	RADIATOR <i>Ren</i>	1	\$ 2,125.00	\$ 2,125.00	+
28	RADIATOR SIDE GARNISH <i>Ren</i>	2	\$ 160.00	\$ 320.00	+
29	BOOTLID <i>Buckled</i>	1	\$ 910.00	\$ 910.00	✓
30	BOOTLID DETECTOR <i>ren</i>	1	\$ 395.00	\$ 395.00	+
31	BOOTLID LAMP <i>lt</i>	2	\$ 420.00	\$ 840.00	-
32	BOOT LTD EMBLEM 'CAMRY' <i>3/10</i>	1	\$ 65.00	\$ 65.00	-
33	BOOT LID EMBLEM '2.4'	1	\$ 60.00	\$ 60.00	-
34	BOOT LID LOGO <i>ren</i>	1	\$ 80.00	\$ 80.00	-
35	BOOTLID HINGE <i>2</i>	2	\$ 126.00	\$ 252.00	+
36	BOOTLID STOPPER <i>2</i>	2	\$ 19.00	\$ 38.00	+
37	BOOTLID INSULATOR <i>1</i>	1	\$ 265.00	\$ 265.00	+
38	BOOTLID LOCK <i>ren</i>	1	\$ 395.00	\$ 395.00	+
39	BOOTLID CATHER <i>ren</i>	1	\$ 25.00	\$ 25.00	+
40	BOOTLID WEATHERSTRIP <i>lt</i>	1	\$ 240.00	\$ 240.00	-
41	REAR NUMBER PLATE GARNISH WITH MOULDING <i>ren</i>	1	\$ 380.00	\$ 380.00	+
42	REAR BUMPER <i>Distorted</i>	1	\$ 560.00	\$ 560.00	-
43	REAR BUMPER REFLECTOR <i>LH lt</i>	2	\$ 75.00	\$ 150.00	75
44	REAR BUMPER SIDE RETAINER (SIDE) <i>LH 2</i>	2	\$ 70.00	\$ 140.00	70
45	REAR BUMPER RETAINER (CORNER) <i>LH 2</i>	2	\$ 80.00	\$ 160.00	80
46	REAR BUMPER SCREW COVER GARNISH <i>2</i>	2	\$ 28.00	\$ 56.00	+
47	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 405.00	\$ 405.00	✓
48	REAR DOOR LH <i>Dented</i>	1	\$ 1,390.00	\$ 1,390.00	-
49	REAR DOOR INNER LOCK LH <i>Found</i>	1	\$ 395.00	\$ 395.00	✓
50	REAR DOOR WEATHER STRIP LH <i>ren</i>	1	\$ 210.00	\$ 210.00	+
51	REAR DOOR INNER TRIM BOARD LH <i>ren</i>	1	\$ 650.00	\$ 650.00	+
52	TAILLAMP <i>LH cruld, RA lt</i>	2	\$ 535.00	\$ 1,070.00	-
53	TAILLAMP PANEL LH <i>Distorted</i>	1	\$ 230.00	\$ 230.00	-
54	REAR FENDER LH <i>Distorted</i>	1	\$ 995.90	\$ 995.90	-
55	REAR FENDER INNER PANEL LH <i>Repair</i>	1	\$ 859.10	\$ 859.10	+

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLA1688L**
 MODEL : **TOYOTA CAMRY**
 DATE OF ACCIDENT : 19.08.2024
 TIME OF ACCIDENT : 09:20 HOURS

56	REAR FENDER INNER COWLING <i>New</i>	2	\$ 405.00	\$ 810.00	+
57	REAR FENDER INNER TRIM <i>Cupled</i>	2	\$ 675.00	\$ 1,350.00	(675)
58	REAR WINDSCREEN MOULDING <i>New</i>	1	\$ 240.00	\$ 240.00	✓
59	REAR END PANEL <i>Distorted</i>	1	\$ 620.00	\$ 620.00	✓
60	REAR END PANEL TOP GARNISH <i>Distorted</i>	1	\$ 420.00	\$ 420.00	✓
61	REAR FLOOR PANEL TOP BOARD <i>torn</i>	1	\$ 280.00	\$ 280.00	✓
62	REAR FLOOR PANEL <i>Distorted</i>	1	\$ 1,140.00	\$ 1,140.00	✓
63	REAR FLOOR INNER SUPPORT PANEL <i>Distorted</i>	1	\$ 385.20	\$ 385.20	✓
64	REAR FLOOR SIDE PANEL LH <i>Distorted</i>	1	\$ 586.20	\$ 586.20	✓
65	REAR SPARE TYRE BOLT <i>Best</i>	1	\$ 32.00	\$ 32.00	✓
66	REAR CHASSIS EXTEND MEMBER LH <i>Distorted</i>	1	\$ 796.00	\$ 796.00	✓

TOTAL PRICE \$ 35,337.40
 LESS 25% \$ 8,834.35
SUB TOTAL PRICE \$ 26,503.05

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Cupled</i>	1	\$ 50.00	\$ 50.00	✓
2	FRONT BUMPER CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	-30
3	BONNET INSULATOR CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
4	FRONT FENDER COWLING CLIPS (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
5	RADIATOR SUPPORT PANEL SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	+
6	RADIATOR COOLANT <i>New</i>	1	\$ 60.00	\$ 60.00	-80
7	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00	+
8	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
9	BOOTLID INSULATOR CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
10	BOOTLID SIDE LINING (SPECAIL TYPE) <i>New</i>	1	\$ 200.00	\$ 200.00	60-
11	REAR DOOR SEALANT <i>New</i>	1	\$ 120.00	\$ 120.00	+
12	REAR DOOR INNER TRIM CLIP <i>New</i>	1	\$ 80.00	\$ 80.00	+
13	REAR DOOR SIDE LINING (SPECAIL TYPE) <i>New</i>	1	\$ 100.00	\$ 100.00	60-
14	TAILLAMP CLIPS (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	+
15	REAR FENDER SEALANT RH <i>New</i>	1	\$ 150.00	\$ 150.00	60
16	REAR FENDER COWLING CLIPS (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
17	REAR FENDER INNER TRIM CLIPS (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	20
18	REAR WINDSCREEN SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	80

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLA1688L**
 MODEL : **TOYOTA CAMRY**
 DATE OF ACCIDENT : 19.08.2024
 TIME OF ACCIDENT : 09:20 HOURS

19	REAR WINDSCREEN INNER SEAL <i>Nw</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
20	REAR END PANEL INSULATION SEAL <i>Nw</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
21	REAR FLOOR PANEL INSULATION SEAL <i>Nw</i>	1	\$ 350.00	\$ 350.00	<i>200</i>
22	REVERSE SENSOR <i>2nd</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

TOTAL \$ 2,200.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	<i>600</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>600</i>
3	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>+</i>
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	<i>60</i>

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	<i>1800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>1200</i>
3	TUFF COAT	\$ 250.00	<i>120</i>
4	WIRING CHECK	\$ 160.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	<i>150</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLA1688L**
 MODEL : **TOYOTA CAMRY**
 DATE OF ACCIDENT : 19.08.2024
 TIME OF ACCIDENT : 09:20 HOURS

8	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
10	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 120.00	✓
11	REMOVE AND REFIX REAR EXHAUST	\$ 180.00	X
12	TRANSFER REAR DOOR MECHANISM	\$ 80.00	40
13	REMOVE & REINSTALL REAR WINDOW GLASS	\$ 80.00	40
14	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	60
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 8,960.00

TOTAL PARTS COST : \$ 28,703.05
 TOTAL LABOUR COST : \$ 8,960.00
 TOTAL REPAIR COST : \$ 37,663.05

Adrian
 2/5 21/08/24
 18 Dup

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: