

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

TP Somp
Xiao Chm.

VEHICLE NO : SNF 6017 R
CHASSIS NO : RG11040870

MAKE / MODEL : HONDA STEP WAGON
ACCIDENT DATE : 19.08.2024

NO	DESCRIPTION	QTY	AMOUNT (\$)
LIST ITEMS			
1	LH roof top side pnel <i>Dented.</i>	1	\$ 1713.53
2	Front door <i>new</i>	1	\$ 1358.76
3	Front door glass <i>cut</i>	1	\$ 585.39
4	Front door inner weather <i>Torn.</i>	1	\$ 143.39
5	Front door glass channel <i>Dented</i>	1	\$ 128.05
6	Front door side mirror <i>Damaged</i>	1	\$ 1041.95
7	Front door side mirror housing <i>new</i>	1	\$ 173.68
8	Front door frame black sticker <i>new</i>	1	\$ 43.42
9	Front door frame side garnish <i>cut</i>	1	\$ 59.28
10	Rear LH door <i>Dented.</i>	1	\$ 1459.38
11	Rear LH door glass <i>Shattered</i>	1	\$ 731.64
12	Rear LH door glass outer moulding <i>new</i>	1	\$ 119.99
13	Rear LH door glass rear side garnish <i>cracked</i>	1	\$ 159.38
14	Rear LH door glass inner rubber <i>cut</i>	1	\$ 224.25
15	Rear LH door glass channel <i>new</i>	1	\$ 142.22
16	Rear LH fender glass <i>Shattered.</i>	1	\$ 731.64
17	Rear LH fender side garnish <i>Dented</i>	1	\$ 265.98
18	Rear LH safety belt garnish <i>new</i>	1	\$ 354.64
19	Roof top upholstery <i>new</i>	1	\$ 1615.77
6290.42			\$ 11052.34
5032.33			\$ 2210.468
LESS 20% DISC			\$ 8841.87
TOTAL			\$ 8841.87

LABOUR COST

1	To supply LH rear fender glass + front windscreen sealant	1	\$ 200.00
2	Remove + refix door glass <i>and fittings.</i>	1	\$ 300.00
3	Remove + refix upholstery	1	\$ 300.00
4	Remove + reinstall rear LH safety belt	1	\$ 100.00
5	Remove + refix windscreen + fender glass	1	\$ 300.00
6	Remove, replace + repair consistent to the accident	1	\$ 1800.00
7	Respray painting	1	\$ 1600.00
8	tuff kote	1	\$ 100.00
9	Towing fee	1	\$ 150.00
TOTAL			\$ 4850.00
GRAND TOTAL			\$ 13691.87

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6892.33
L/S: 55K
5.5K

Adrim h
L/S 20/08/24
07 Days.