



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0625/2024/KS
DATE : 20-Aug-24
WIP : 27711

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : AZNI BIN MARMIM
ADDRESS : BLK 315A PUNGGOL WAY
#03-641
SINGAPORE 821315
TELEPHONE : HP +65 96851674
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230071311-01
VEHICLE NO : **SNL 6399 G**
MODEL CODE : A3 SPORTBACK 1.0 TFSI
MODEL YEAR : 24/7/2023
ENGINE NO : DLA E12385
CHASSIS NO : WAUZZZGY9NA099008
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Aug-24
PLACE OF ACCIDENT : TAMPINES RD, TOWARDS KPE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNL 6399 G.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 /	
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00 /	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,450.00 / 1000	
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.	\$ 2,450.00 / 1650	
6	TO REMOVE AND REINSTALL FRONT WHEEL SUSPENSION ASSY.	S/N \$ 3,200.00 ?	
7	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00 ?	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00 /	
TOTAL LABOUR CHARGES		: \$ 10,022.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNL 6399 G.

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de</i>	1	\$	1,889.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	311.00
3	FRONT BUMPER BRACKET <i>?</i>	1	\$	36.00
4	FRONT BUMPER CLOSIGN ELEMENT - RH <i>?</i>	1	\$	145.00
5	FRONT BUMPER CLOSING ELEMENT - LWOER CENTRE <i>?</i>	1	\$	298.00
6	FRONT BUMPER AIR GUIDE - RH <i>X</i>	1	\$	75.00
7	FRONT BUMPER SPOILER <i>?</i>	1	\$	366.00
8	FRONT BUMPER COVER TRIM - RH <i>X</i>	1	\$	117.00
9	FRONT BUMPER AIR GUIDE GRILLE - RH <i>?</i>	1	\$	192.00
10	FRONT AIR GUIDE GRILLE DUMMY COVER - RH <i>X</i>	1	\$	41.00
11	FRONT AIR GUIDE GRILLE PARKING AID SENSOR - RH <i>?</i>	1	\$	300.00
12	FRONT PARKING AID SENSOR SEAL RING <i>X</i>	4	\$	57.00
13	FRONT BUMPER GUDIE SECTION - RH <i>?</i>	1	\$	61.00
14	LED HEADLIGHT - RH <i>cut photo?</i>	1	\$	4,583.00
15	LIFT CYLINDER - RH <i>?</i>	1	\$	230.00
16	LIFT CYLINDER HOSE - RH <i>X</i>	1	\$	118.00
17	FRONT FENDER - RH <i>bl</i>	1	\$	1,318.00
18	FRONT FENDER CLOSING ELEMENT - RH <i>?</i>	1	\$	36.00
19	FRONT FENDER RIVET - RH <i>nu</i>	3	\$	13.00
20	FRONT FENDER BRACKET - RH <i>?</i>	1	\$	56.00
SUB TOTAL SPARE PARTS		:	\$	10,242.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNL 6399 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - RH ?	1	\$	56.00
22	FRONT FENDER BRACKET - RH ?	1	\$	45.00
23	FRONT FENDER BRACKET - RH ?	1	\$	122.00
24	FRONT FENDER ATTACHMENT PARTS - RH X	1	\$	135.00
25	FRONT WHEEL HOUSING LINER SEAL - RH ?	1	\$	43.00
26	FRONT WHEEL HOUSING LINER - RH ?	1	\$	204.00
27	WHEEL HOUSING LINER ATTACHMENT PARTS - RH ?	1	\$	139.00
28	FRONT ALUMINIUM RIM - RH sc	1	\$	1,614.00
29	FRONT ALUMINIUM RIM RUBBER VALVE - RH re	1	\$	5.00
30	FRONT LOWER ARM - RH ?	1	\$	422.00
31	FRONT STABILIZER , COMPLETE ?	1	\$	479.00
32	FRONT WHEEL BEARING HOUSING - RH ?	1	\$	669.00
33	FRONT WHEEL HUB ?	1		TBC
34	FRONT GUIDE JOINT - RH ?	1	\$	145.00
35	FRONT COUPLING ROD - RH ?	1	\$	112.00
36	FRONT LOWER ARM COVER - RH ?	1	\$	11.00
37	DRIVESHAFT - RH ?	1	\$	2,393.00
38	STEERING GEAR ?	1	\$	6,300.00
39	HEAT SHIELD PLATE ?	1	\$	158.00
40	SUBFRAME ?	1	\$	939.00
41	SUBFRAME BUSHES ?	1	\$	189.00
42	FRONT TYRE - RH X	1		TBC
43	SUNDRIES ?	1	\$	1,000.00
TOTAL SPARE PARTS		:	\$	25,422.00
TOTAL LABOUR CHARGES		:	\$	10,022.00
GRAND TOTAL		:	\$	35,444.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Repair - Hp 90010668
: 21/08/24
: Sclump
: Repair
: Per 64 pit / Excess: TRA

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT