

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

Not Authorized
all
moray
21/8/24
2/5 7100/
take photo of the sign.
4 days.

VEHICLE NUMBER: EF2858M
MAKE & MODEL: JAGUAR XF

BOOTLID
BOOTLID LOGO C/W JAGUAR EMBLEM
BOOTLID OUTER GARNISH
BOOTLID LAMP L/R X2
BOOTLID INNER TRIM
BOOTLID HINGE L/R X2
BOOTLID NUMBER PLATE LAMP L/R X2
BOOTLID INNER LOCK
BOOTLID LOCK STRIKER
BOOTLID WEATHERSTRIP
TAIL LAMP L/R X2
REAR BUMPER
REAR BUMPER LOWER (BLACK)
REAR BUMPER SIDE RETAINER L/R X2
REAR BUMPER CENTRE BRACKET
REAR BUMPER BRACKET L/R X2
REAR BUMPER REINFORCEMENT
END PANEL
END PANEL GARNISH
SPARE TYRE PANEL TOP BOARD
SPARE TYRE PANEL
REAR EXHAUST MUFFLER CHROME TIP L/R X2
REAR EXHAUST MUFFLER
REAR EXHAUST RUBBER HANGER X2

1100
2680
850

1200
1880

n/sa1 o/s cno
DD/70.1
gratd

Perf/4ur
DD 13erf

R	\$3,811.80	X
11	\$211.50	X
11	\$538.10	X
11	\$1,466.20	X
11	\$656.10	X
11	\$423.20	X
11	\$356.80	X
11	\$617.20	X
11	\$156.70	X
11	\$512.90	X
	\$2,956.60	12 C
	\$2,855.60	—
	\$986.10	—
	\$387.40	X
	\$211.10	—
	\$178.60	X
	\$2,610.70	—
	\$2,312.60	—
	\$897.70	X
	\$1,215.20	X
	\$2,156.80	X
	\$646.20	X
	\$1,925.10	X
	\$188.00	X
	\$28,278.20	
Less 10%	\$2,827.82	
	\$25,450.38	

REAR REVERSE SENSOR
REAR REVERSE CAMERA
REAR NUMBER PLATE WITH GARNISH (CHROME)
REAR BUMPER CLIPS
REAR BOOTLID INNER TRIM CLIPS
END PANEL GARNISH CLIPS
END PANEL SEALANT
SPARE TYRE PANEL SEALANT

500	\$280.00	X
11	\$350.00	X
11	\$120.00	X
11	\$60.00	40 S/W
11	\$50.00	X
11	\$60.00	X
11	\$100.00	X
11	\$100.00	X
	\$1,120.00	

TO CHECK REAR WIRING
TO REPLACE REAR REVERSE SENSOR
TO REMOVE AND REFIT REAR REVERSE CAMERA

	\$50.00	20
	\$80.00	30
11	\$100.00	X

TO REMOVE AND TRANSFER BOOTLID FITTINGS TO NEW
 TO REMOVE AND REFIT REAR INTERIOR TRIMS
 TO REMOVE AND REPLACE REAR EXHAUST MUFFLER
 TO PROVIDE LABOUR, WORKMANSHIP
 TO SPRAY PAINT ON AFFECTED PANELS (SPECIAL PAINT)
 RUST PROOFING

1^ \$150.00 X
 \$160.00 60
 1^ \$150.00 X
 \$1,600.00 800
 \$2,000.00 800
 \$150.00 30
\$4,440.00

Total

\$31,010.38

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

p- 7921.1
 102
 712859
 40
 1740
 8908.59
 292
 7127