



ASSESSMENT FOR REPAIR : FBR7627C
HONDA ADV150 ABS
COE EXPIRY : 06.10.2030

21 AUG 2024
Lump Sum / Part by Part

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	HANDLE BAR	110.00	✓		
1	LH - MIRROR	40.88	✓		
1	LH - LEVER	40.88	✓		
1	LH - BAR END	70.88	✓		
1	LH - FRONT SIGNAL	76.38	✓		
1	LH - FRONT COWL (GLOSS RED)	190.75	✓		
1	LH - LEG SHIELD COWL (MATT BLACK)	109.00	✓		
1	AIR BOX COVER (BIG PIECE)	76.38	✓		
		715.13			

Special Nett Items

STEERING CONE & BEARING	130.00	✓		
FRONT FORK ALIGNMENT	230.00	✓		
WHEEL ALIGNMENT	130.00	✓		
FRAME ALIGNMENT	210.00	✓		
	700.00			

Total Parts 1,415.13

Labour Charges

1	Workmanship to renew damage parts & areas	400.00	180
	\$100 per days X 4 days	400.00	

Total Parts & Labours Concluded 1,815.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
 9009 6608
 21/8/24
 L/S S
 2 days

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com