

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email: shawn7530@hotmail.com

21 Aug 2024

Vehicle No.: SLQ 6409 J

Model: Mercedes Benz CLA180

not Authorized
for
merang

22/8/24

1/5 @ 8600

4 days.

QTY

DESCRIPTION

AMT S\$

List Items

1	Front door -RH	Body	\$	2,872.00 ✓
1	Front door glass outer chrome moulding	new	\$	185.00 ✓
2	Front door hinges	11	\$	336.00 X
1	Front door inner trim board	2e/cro	\$	1,080.00 ✓
1	Front door inner lock	su	\$	485.00 X
1	Front door outer handle	su	\$	525.00 X
1	Front door regulator	Dange	\$	650.00 ✓
1	Front door regulator motor	11	\$	590.00 X
1	Front door rubber	new	\$	286.00 ✓
1	Front door side mirror	R	\$	1,400.00 X
1	Rear door -RH	10/5ent	\$	2,754.00 ✓
1	Rear door glass outer chrome moulding	new	\$	175.00 ✓
2	Rear door hinges	11	\$	336.00 X
1	Rear door inner trim board	11	\$	1,050.00 X
1	Rear door inner lock	11	\$	525.00 X
1	Rear door outer handle	11	\$	490.00 X
1	Rear door rubber	new	\$	330.00 ✓
1	Rear windscreen repair kit (1 set)	11	\$	198.00 X
1	Rear bumper	cut/brn	\$	2,485.95 ✓
1	Rear bumper bracket	11	\$	70.00 X
1	Rear bumper side retainer	11	\$	95.00 X
1	Rear fender -RH	R	\$	2,300.00 X
1	Rear fender inner shield	11	\$	175.00 X
1	Rear wheel rim -RH	R	\$	1,960.00 X
			102	\$ 21,352.95
			Less 5%	\$ 1,067.65
				\$ 20,285.30

1796.42

Special Nett Items

1	Rear windscreen sealant	11	\$	80.00	X
1	Rear bumper clip (1 set)	111	\$	120.00	40
1	Rear fender inner shield clip (1 set)	11	\$	80.00	X
1	Rear tyre	11	\$	500.00	X
			\$	780.00	

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$ 11	180.00	X
3	To remove and refit rear reverse sensor.	\$	150.00	30
4	To conduct wheel alignment.	\$	150.00	60
5	To remove and refit rear windscreen glass.	\$ 11	180.00	X
6	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	400.00	120
7	To apply undercoating.	\$	150.00	60
8	Panel beating.	\$	1,600.00	500
9	To re-spray painting on the affected areas.	\$	1,500.00	900
			\$	4,390.00

Grand Total : \$ 25,455.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-10128-42
102
9115.58
40
1690
10845.58
202
8676