



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGJ165Y

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

20231

SGJ165Y / 08/11/2019

03/09/2024/ 71486

WDD2050402R5053768

27491031788544

MB/MB C 180 AVANTGARDE/AVANTGARDE

029 996 DesignoHyac/ 041 115 ARTICOSpSea

| Account No | Terms | Date/Time Printed | CSE | Operator | Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|------------|--------|-------------------|-----|------------------|------------------------------------------------------------------------|-----|------------|-------|---------|
| WF001862 | Credit | 07/01/2025/ 08:12 | K0 | 301 / Kerlyn Ong | | | | | |
| Z REQUEST | | | | | Customer Request | | | | |
| M BPNSUN | | | | | POLICY NO/ACC DATE : D23MTPV01014524 // 17/08/2024 | | | | |
| | | | | | DRIVE IN/TP VEH NO. : 19/08/2024 // SHB5244A - FIRST CAPITAL | | | | |
| | | | | | DATE IN/DATE SURVEY: 03/09/2024 1730 // LKK - RASUL | | | | |
| | | | | | DIRECT SETTLEMENT : 29/08/2024 // FIRST CAPITAL - Rachel Wu | | | | |
| A BPILAB | | | | | STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT | | | | 5760.00 |
| | | | | | DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. | | | | |
| A BPIRES | | | | | RESPRAY RH/ FRONT FENDER, RH/ FRONT DOOR, RH/ REAR DOOR, RH/ REAR | | | 0.02 | 4000.00 |
| | | | | | FENDER, REAR BUMPER | | | | |
| A BPILAB | | | | | USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO | | | 0.10 | 380.00 |
| | | | | | IDENTIFICATION STANDARD. NETT | | | | |
| A BPILAB | | | | | REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT | | | 0.05 | 800.00 |
| A BPILAB | | | | | CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT | | | | 120.00 |
| A BPILAB | | | | | REMOVE & REFIT LUGGAGE COMPARTMENT,TRIM, GARNISH- | | | | 960.00 |
| | | | | | CARPET FOR NECESSARY REPAIR.NETT | | | | |
| A BPILAB | | | | | BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS SEAL. | | | | 120.00 |
| A BPILAB | | | | | CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM. NETT | | | | 180.00 |
| A BPILAB | | | | | TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT | | | | 540.00 |
| S BPNSUB | | | | | TRANSFER RIM AND BALANCING TYRE. NETT | | | | 60.00 |
| | | | | | SUPPLY LABOUR FOR INSTALLATION. | | | | |
| | | | | | DO NO:344593 | | | | |

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGJ165Y

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No **20231**
Reg No/Reg Date **SGJ165Y / 08/11/2019**
Date In/Mileage **03/09/2024/ 71486**
Chassis No **WDD2050402R5053768**
Engine No **27491031788544**
Make/Model **MB/MB C 180 AVANTGARDE/AVANTGARDE**
Colour/Trim **029 996 DesignoHyac/ 041 115 ARTICOSpSea**

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|------------------|
| WF001862 | Credit | 07/01/2025/ 08:12 | K0 | 301 / Kerlyn Ong |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|-------------------------------------|------|------------|-------|---------|
| M. BPNSUN | | | | 15.00 |
| SUNDY | | | | |
| X RH/ FRONT DOOR | 1.00 | 2322.82 | 00.00 | 2322.82 |
| X RH/ FRONT DOOR SEAL | 1.00 | 335.72 | 00.00 | 335.72 |
| X RH/ FRONT DOOR SELF-ADHESIVE TRIM | 1.00 | 29.78 | 00.00 | 29.78 |
| X RH/ FRONT DOOR ORNAMENTAL MOLDING | 1.00 | 232.21 | 00.00 | 232.21 |
| X RH/ REAR DOOR | 1.00 | 2876.98 | 00.00 | 2876.98 |
| X RH/ REAR DOOR SEAL | 1.00 | 335.72 | 00.00 | 335.72 |
| X RH/ REAR DOOR SELF-ADHESIVE TRIM | 1.00 | 29.78 | 00.00 | 29.78 |
| X RH/ REAR DOOR ORNAMENTAL MOLDING | 1.00 | 197.21 | 00.00 | 197.21 |
| X RH/ REAR FENDER | 1.00 | 3104.83 | 00.00 | 3104.83 |
| X RH/ REAR FENDER VENT FLAP | 1.00 | 47.37 | 00.00 | 47.37 |
| X RH/ REAR FENDER INSULATION | 1.00 | 66.63 | 00.00 | 66.63 |
| X RH/ REAR DISK WHEEL | 1.00 | 1541.34 | 00.00 | 1541.34 |
| X BLIND RIVET | 6.00 | 1.85 | 00.00 | 11.10 |
| X SEAM SEAL | 1.00 | 123.74 | 00.00 | 123.74 |

Confirmed & accepted by

Finalization

9% GST on **24190.23** **2177.12**
Nett 24,190.23
Total Payable 26,367.35

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG