

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : MUHAMMAD THORIQ BIN
AZHAM (0174689259)

Accident Date : 12-Aug-24

Vehicle No : JRM6776 (DOR: 150616)

Vehicle Model : Yamaha Nmax

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fork assy Bent/tu1	\$ 680 980.00 ✓
1	Fork under bracket Buy	\$ 180 220.00 ✓
1	Front sport rim neged	\$ 340 550.00 ✓
1	Front brake disc 11	\$ 230.00 x
1	Brake caliper 11	\$ 585.00 x
1	Front rim shaft Buy	\$ 50 105.00 ✓
1	Front rim bearing New	\$ 60 180.00 ✓
1	Windshield 320	\$ 248.00 ✓
1	Windshield Cover Cut	\$ 155.00 ✓
1	Headlamp (LED) One	\$ 980.00 ✓
1	Lamp Stay Buy	\$ 205 385.00 ✓
1	Side mirror 310	\$ 120 180.00 ✓
1	Handle-bar Buy	\$ 250.00 ✓
1	Handle-bar balancer set Cu)	\$ 48 125.00 ✓
1	Hand grip (1 set) 11	\$ 80.00 x
1	Brake levers (1 set) Cut	\$ 90 150.00 ✓
1	Front signals - 1 set One	\$ 160 295.00 ✓
1	Front side cover matt (1 set) Cu	\$ 148 220.00 ✓
1	Front center lower cover Cut	\$ 190 285.00 ✓
1	Radiator cover Svc	\$ 155.00 x
1	Exhaust assy DO	\$ 850.00 ✓
1	Exhaust protector M.S	\$ 110 165.00 ✓
2	Footstep panels Dis	\$ 330.00 ✓
2	Footstep lower cover Dis	\$ 310.00 ✓
1	Rear Footrest (1 set) Svc	\$ 180.00 x
1	Fairing cover (1 set) Dis	\$ 820 1,320.00 ✓
		\$ 9,513.00
Less 10%		\$ 951.30
		\$ 8,561.70

Special Net Items

EROFIA MOTOR TRADING PTE LTD^(201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

MUHAMMAD THORIQ BIN

Owner : AZHAM (0174689259
)

Accident Date : 12-Aug-24

Vehicle No : JRN6776 (DOR: 150616)

Vehicle Model : Yamaha Nmax

Estimated Repair Costs

Special Net Items


1	Number plate (1 set)	<i>nm</i>	\$	38.00	<i>10</i>
2	Fork oils	<i>nm</i>	\$	30.00	<i>X</i>
2	Fork oil seals	<i>nm</i>	\$	56.00	<i>X</i>
1	Steering cone (1 set)	<i>nm</i>	\$	120.00	<i>60</i>
1	Spotlight	<i>320 KIV</i>	\$	280.00	<i>140 X</i>
			\$	524.00	

<u>S/No.</u>	<u>Labour</u>				
1	To provide towing service (LOD) \$50.00	<i>refer LOD</i>	\$	-	<i>X</i>
2	To check wiring and reset headlamp focusing		\$	<i>17</i> 80.00	<i>X</i>
3	To provide labour		\$	480.00	<i>350</i>
4	To repair body frame		\$	<i>17</i> 450.00	<i>X</i>
			\$	1,010.00	

Grand Total

\$ 10,095.70

Singapore Dollars: Ten Thousand Ninety-Five and Cents: Seventy only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: