

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST: S2832105J RCB NO: 201327339E

M/S : HSBS Life (Singapore) Pte Ltd
 10 Marine Boulevard
 Marina Bay Financial Centre Tower 2
 #48-01 Singapore 018983

TEL: - FAX: -

ATTN: Motor Claim Department

Your Ref No: WEE GUAN CONST PL

Claim Type: Third Party

Accident Date: 15/06/2023

TP Veh Reg No: SHA8385L

Estimate No: ES1602030
 Date: 24 Jun 2024
 Policy No: 2022-v010293-vcv
 Veh Reg No: XE7686P
 Make/Model: CAMC HN3251X40D1M6
 Chassis No: LZ5N2DD38NB001955
 Engine No: CM6D2840060122A60012
 Reg. Date: 27/09/2022

Estimate Repair Cost to Vehicle No :XE7686P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 Front Bumper	2,588.78	1 PC	2,588.78	
2 Front Lamp Grille	875.68	1 PC	875.68	
3 Front Bumper Sensor -LH	788.68	1 PC	788.68	
4 Step Panel Aluminium Lower -LH	937.55	1 PC	937.55	
5 Step Panel Aluminium Holder Lower -LH	1,108.55	1 PC	1,108.55	
6 Stand Panel -LH	1,255.67	1 PC	1,255.67	
7 Stand Panel Reflector -LH	375.68	1 PC	375.68	
			7,930.59	7,930.59
Labour				
8 Labour to knock & renew all above parts .	1,000.00	1 -	1,000.00	320
9 To rust proofing on affected area .	680.00	1 -	680.00	
10 To spray & painting on affected area .	850.00	1 -	850.00	400
			2,530.00	2,530.00
Total				S\$ 10,460.59
Add GST @ 9%				941.45
Total Amount Payable				S\$ 11,402.04

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND FOUR HUNDRED AND TWO AND CENTS FOUR ONLY

For HUP LIAN HUAT ENGINEERING WORKS

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
 dr
 merans
 21/6/24
 2/5 \$ 3000
 2 days
 take photo. After repair

P-3387-55
 100
 304880
 720
 376880
 202
 3000