



Address: 2 Kaki Bukit Ave 2, #01-08, S(417921)
 Contact Person: Eric Wang
 Contact Number: 80868911
 Email: apexmotorworks911@gmail.com
 UEN: UEN: 53484790X

APEX MOTORWORKS

To:

STER (CLKK)
 22/8/24, 11.30 am

Date: 22/8/2024

Vehicle No: FBP 8839L

Model: MT-15

LIS
 by AL sy, 4 days

Estimated Repair Cost For FBP 8839L (Yamaha MT-15)

QTY	Parts	Amount(SGD)
1 set	Front cast wheel / BT	\$ 860.00
	Front axel / BT	\$ 48.00
	Front brake disc / x nn	\$ 228.00
	Front Disc calipier / CVT	\$ 150.00
	Front brake master pumb and reservoir / CVT	\$ 176.00
	Front brake master pumb connecting pipes & hoses X nn	\$ 50.00
	Front Fender / GR	\$ 217.00
	Front cowling / GR	\$ 105.00
	Radiator / NN	\$ 1,065.00
	Handle bar bracket / GR	\$ 320.00
	Handle bar / RR	\$ 265.00
	Handle bar grip (Set) / GR	\$ 68.00
	Handle bar balancer / GR	\$ 46.00
	Clutch lever (Yamaha MT-15) / GR	\$ 68.00
	Brake lever / BT	\$ 68.00
	Rear brake padal / BT	\$ 48.00
	Front foot rest / BT	\$ 105.00
	Rear view mirror / GR	\$ 110.00
	Left handle bar switch / GR	\$ 140.00
	Right Handle bar switch / GR	\$ 145.00
	Throttle cables and grip set / GR	\$ 85.00
	Main steering lock / GR	\$ 395.00
	Meter / CVT	\$ 1,205.00
	Head lamp / GR	\$ 1,390.00
	Head lamp stay / BT	\$ 185.00
	Fork (set) / BT	\$ 1,650.00
	Fork under bracket / BT	\$ 929.00
	Front Signal lamp Set / GR	\$ 150.00
	Gear lever / BT	\$ 148.00
	Foot brake lever / BT	\$ 115.00

Parts Sum: \$ 10,534.00
 Parts Less 5%: \$ 526.70
 Parts Total: \$ 10,007.30

10,256.00



Address: 2 Kaki Bukit Ave 2, #01-08, S(417921)
 Contact Person: Eric Wang
 Contact Number: 80868911
 Email: apexmotorworks911@gmail.com
 UEN: UEN: 53484790X

APEX MOTORWORKS

To:

Vehicle No:

Model:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimated Repair Cost For FBK2671T (SYM Joyride 200i Evo CVT)

QTY	Parts	Amount(SGD)
1 set	Side stand X	\$ 98.00
	Main Stand X	\$ 105.00
	Fuel tank side cover / BR	\$ 85.00
	Fule tank coving / BR	\$ 110.00
	Fuel tank side cover / BR	\$ 205.00
	Tail cover / CUT	\$ 120.00
	Exhaust muffler / cover / CUT	\$ 650.00
	SPECIAL NETT	
	Front axel nut	\$ 15.00
	Front brake disc mounting bolts	\$ 15.00
	Calipier mounting bolts	\$ 15.00
	Front brake master pump bolts	\$ 15.00
	Front fender mounting	\$ 15.00
	Front cowlng mounting bolts and nuts	\$ 15.00
	Radiator mounting bolts	\$ 15.00
	Tail box	\$ 350.00
	Tail box bracket	\$ 150.00
	Rim Set	\$ 860.00
	Front tyre	\$ 150.00
	Emblem	\$ 29.00
	LABOUR	
	Labour to remove and replace affected components	\$ 900.00
	Spray paint	\$ 600.00
	Chassis alignment	\$ 850.00

Parts Sum: \$ 5,367.00

Parts Less 5%: 0

Parts Total: \$ 15,374.30

12,990.00

520

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC

APC