



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130  
Tel: 9450 7920  
\* zoomautowerks@gmail.com

Not Authorized

for  
Mercedes

21/8/24

d/s \$2900  
the ph. After rep  
4 days.

30 September 2024

REG NO.: SLU 9856 K  
MAKE/MODEL: TOYOTA C-HR

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY        | DESCRIPTION                                 | AMT(\$)            |
|------------|---------------------------------------------|--------------------|
| LIST ITEMS |                                             |                    |
| 1          | Rear tailgate                               | \$ R 1,328.20 X    |
| 2          | Rear tailgate dampers                       | \$ 11 339.60 X     |
| 1          | Rear tailgate inner board                   | \$ 11 400.80 X     |
| 2          | Rear tailgate lamps                         | \$ 11 1,142.80 X   |
| 1          | Rear tailgate lock                          | \$ 11 389.00 X     |
| 1          | Rear tailgate logo                          | \$ 11 167.30 X     |
| 1          | Rear tailgate outer garnish                 | \$ 11 1,218.50 X   |
| 1          | Rear tailgate rubber                        | \$ 11 300.80 X     |
| 1          | Rear tailgate "C-HR" emblem                 | \$ 8 167.30 X      |
| 1          | Rear tailgate "HYBRID SYNERGY DRIVE" emblem | \$ 5 91.00 X       |
| 1          | Rear tailgate inner pull pocket             | \$ 11 80.50 X      |
| 2          | Rear taillamps                              | \$ 11 1,476.60 X   |
| 1          | Rear end panel                              | \$ R 988.60 X      |
| 1          | Rear end panel inner garnish                | \$ 11 266.60 X     |
| 1          | Rear keyless sensor                         | 298.50 \$ C 400.70 |
| 1          | Rear bumper                                 | 702.30 \$ 899.79   |
| 2          | Rear bumper brackets                        | \$ 15 81.40 X      |
| 1          | Rear bumper centre grille cover             | 182.50 \$ 288.30   |
| 1          | Rear bumper lower garnish                   | 481.50 \$ 557.70   |
| 2          | Rear bumper reflector                       | \$ 11 240.60 X     |
| 2          | Rear bumper reflector garnishes             | \$ 11 175.20 X     |
| 1          | Rear bumper reinforcement                   | \$ 35 385.20       |
| 2          | Rear bumper side retainers                  | \$ 11 175.08 X     |
| 2          | Rear bumper PDC sensors                     | 285 \$ 570.00      |
| 1          | Rear bumper tow hook cover                  | 68.00 \$ 91.00     |
| 1          | Rear floor board                            | \$ 11 900.30 X     |
| 2          | Rear fender wheel arch garnishes            | \$ 250 500.42      |
|            |                                             | \$ 13,623.29       |
| Less 25%   |                                             | \$ 3,405.82        |
|            |                                             | \$ 10,217.47       |

**SPECIAL NETT ITEMS**

- 1 Rear windscreen inner seal  
 1 Rear windscreen sealant  
 1 Rear bumper clip (1 set)  
 1 Rear number plate with holder

|    |    |               |    |
|----|----|---------------|----|
| \$ | 11 | 85.00         | X  |
| \$ | 11 | 80.00         | X  |
| \$ | 11 | 80.00         | 40 |
| \$ | 11 | 50.00         | X  |
| \$ |    | <u>295.00</u> |    |

**S/N****LABOUR CHARGES**

- 1 To remove, replaced damaged lamps and check up rear wiring.  
 2 To remove and refit inner garnishes.  
 3 To remove and refit rear reverse sensor.  
 4 To transfer rear tailgate mechanism and wiring assembly.  
 5 To remove and refit rear windscreen glass.  
 6 To apply undercoating.  
 7 Panel beating.  
 8 To re-spray painting on the affected areas.

|    |    |                 |     |
|----|----|-----------------|-----|
| \$ |    | 80.00           | 20  |
| \$ |    | 180.00          | 60  |
| \$ |    | 120.00          | 30  |
| \$ | 11 | 80.00           | X   |
| \$ | 11 | 180.00          | X   |
| \$ | 11 | 150.00          | X   |
| \$ |    | 1,400.00        | 580 |
| \$ |    | <u>1,300.00</u> | 720 |
| \$ |    | 3,490.00        |     |

**GRAND TOTAL :****\$ 14,002.47**

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2903.42  
 242  
2177.57  
 40  
 1410  
3627.57  
 242  
2902