



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080345/Kvp3e2
16 RAFFLES QUAY	Date:	29/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1412C	Veh. Inspected	SHB 9779Y
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007333MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	21/08/2024

2. Vehicle Details

Make & Model	TOYOTA ALPHARD (A)	C.C	2493
Engine No.	2AR2219984	Year of Reg.	17/12/2019
Chassis No.	AYH300089929	Colour	METALLIC WHITE
Odometer	521642 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/65R16	SAILUN	9
L/H Front Tyre	215/65R16	SAILUN	9
R/H Rear Tyre	215/65R16	WANLI	9
L/H Rear Tyre	215/65R16	WANLI	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2024	Inspection Date	21/08/2024
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days