

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9779Y

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

21 AUG 2024

SHB9779Y

AYH300089929

200303878K

TOYOTA

ALPHARD

19/08/24

SHC14120/FCI.

17/12/2019

	PART
1	COVER, REAR BUMPER, UPR RH
1	COVER, REAR BUMPER, UPR LH
1	REAR BUMPER
1	BUMPER, REAR COVER
1	SUPPORT, REAR BUMPER SIDE, RH
1	SUPPORT, REAR BUMPER SIDE, LH
1	REFLECTOR ASSY, LH
1	REAR END PANEL
1	LAMP ASSY, REAR COMBINATION, RH
1	LENS AND BODY, REAR LAMP, RH
1	LAMP ASSY, REAR COMBINATION, LH
1	LENS AND BODY, REAR LAMP, LH
1	PANEL SUB ASSY, REAR DOOR, LH
1	RR WINDSCREEN GLASS
1	TAILGATE
1	LOCK ASSY, BACK DOOR
1	BOARD ASSY, BACK DOOR TRIM
1	PARKING AID, SENSOR ULTRASONIC
1	FENDER PANEL REAR LH
1	LINER, REAR WHEEL HOUSE, LH
1	PLATE, BACK DOOR - Alphard
1	PLATE, BACK DOOR - E- FOUR
1	EMBLEM SUB-ASSY

	LIST
\$	1m 314.00 X
\$	Bu 314.00 ✓
\$	Bz 2,909.48 ✓
\$	1m 290.30 X
\$	1m 240.00 X
\$	0.1 240.00 ✓
\$	CM 77.20 ✓
\$	Bz 781.70 ✓
\$	1m 861.10 X
\$	1m 678.00 X
\$	1m 861.10 X
\$	1m 678.00 X
	no items 3,999.52 X
\$	1m 1,948.10 X
\$	Bz 2,040.50 ✓
\$	Net 800.20 ✓
\$	Net 734.50 ✓
\$	1m 785.60 ✓
\$	R 2,129.54 X
\$	1m 330.40 X
\$	1m 52.00 ✓
\$	1m 41.00 ✓
\$	1m 72.40 ✓
TOTAL \$ 21,013.24	

Not Authored
11 Rm @ 7200/r
Return After Repair
5 days

Trans-cab Auto Services Pte Ltd

AAD2408-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9779Y

25% 10% \$ 2,101.32
\$ 18,911.92

Special Nett

1	REAR BUMPER CLIP	\$ <i>mu</i>	65.00	✓
1	END PANEL INNER TRIM CLIP	\$ <i>mu</i>	60.00	✓
1	REAR BUMPER PROTECTOR	\$ <i>NIP</i>	180.00	X
2	WINDSCREEN SEALANT	\$ <i>mu</i>	150.00	405m
1	WINDSCREEN MOULDING	\$ <i>mu</i>	200.00	✓
1	WINDSCREEN INNER SPONGE SEAL	\$ <i>mu</i>	130.00	305m
TOTAL		\$	785.00	

TOTAL PARTS \$ **785.00**

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,000.00 *700l*

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ 170.00 *120l*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 170.00 *80l*

To check steering geometry and computer wheel alignment

\$ *mu* 220.00 X

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 180.00 *60l*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *mu* 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2408-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9779Y

Putty and spray painting of the affected portion.	\$	3,000.00	8801
To reinstall rear bumper parking sensor.	\$	170.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	601
TOTAL	\$	7,630.00	

Over All Total \$ 27,326.92**PART BY PART (REPAIR DAY) 10 days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: