

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS MS FIRST CAPITAL INSURANCE LTD Ref: CS3/FCI24080346/Knp3e2 16 RAFFLES QUAY Date: 28/08/2024 #42-01 HONG LEONG BUILDING SINGAPORE 048581 Code: FCI2 1. **Policy Particulars :- PRE-REPAIR SURVEY** Insured Veh. SHA 5170J Veh. Inspected FBG 4951T Policy No. D-24101861MFCT Coverage 0 Claim No. D24007229MFCT **Excess** \$0.00 **Assign From** CAROLINE Assign Date 21/08/2024 2. **Vehicle Details** C.C Make & Model 150 YAMAHA YZF-R15 Engine No. 1CK1023351 Year of Reg. 14/08/2012 Chassis No. ME11CK015C2023348 **BLUE / WHITE** Colour Odometer IN ORDER 118166 KM Steering **Brakes** IN ORDER GOOD General Modification(s) RIMS: STANDARD ALLOY RIM **Conditions of Tyres** 3. Size Make Balance (mm) 80/90 R17 **NORTON R/H Front Tyre** 2 L/H Front Tyre 3 R/H Rear Tyre 130/70 R17 **PIRELLI** L/H Rear Tyre **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. 5. **General Information Accident Date** 14/08/2024 **Inspection Date** 22/08/2024 (10:19) Survey held at HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$9,000.00 (EST) E)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 **Estimate Days of Repair** ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

KSC

KENNETH KONG SENG CHEONG