



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LONPAC INSURANCE BHD		Ref:		CS3/LPC24080349/Kvh3m4
300 BEACH ROAD		Date:		09/09/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555		Code:		LPC2
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	GW 7288L	Veh. Inspected	SNJ 3204R	
Policy No.	Z23VC05020310	Coverage	0	
Claim No.	23/24/24/VC05/029722	Excess	\$0.00	
Assign From	CHARMAINE KONG	Assign Date	21/08/2024	
2. Vehicle Details				
Make & Model	TOYOTA RAIZE 1.0X CVT	C.C	996	
Engine No.	1KRK023011	Year of Reg.	10/01/2023	
Chassis No.	A200A0021717	Colour	WHITE	
Odometer	22722 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	215/60R16	DUNLOP	7	
L/H Front Tyre	215/60R16	DUNLOP	7	
R/H Rear Tyre	215/60R16	DUNLOP	8	
L/H Rear Tyre	215/60R16	DUNLOP	8	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
5. General Information				
Accident Date	19/08/2024	Inspection Date	22/08/2024 (09:49)	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.